DA AUG 2022

DATS NO.



Republic of the Philippines

Department of Environment and Natural Resources NE JAHNO

MIMAROPA Region

PROVINCIAL ENVIRONMENT AND NATURAL RESOURCES OFFICE

Bgy. Sta. Monica, Puerto Princesa City, Palawan

Telfax No. (048) 434 - 8791

Email Add: penropalawan@denr.gov.ph

RED

July 25, 2022

MEMORANDUM

FOR : The Regional Executive Director

DENR MIMAROPA Region 1515 L&S Bldg., Roxas Blvd.

Ermita, Manila

: The Regional Director

MGB –MIMAROPA Region 1515 L&S Bldg., Roxas Blvd.

Ermita, Manila

FROM : Provincial Environment and

Natural Resources Officer

SUBJECT: ONSITE VISIT ON THE PROPOSED CONCRETING OF THE

BARANGAY ROAD LOCATED AT BARANGAY DEBANGAN,

TAYTAY, PALAWAN


Forwarded is the Memorandum dated 18 July 2022 of CENRO Taytay transmitting the memorandum dated 15 July 2022 from Francis Jade R. Cometa, Science Research Specilaist II, MGB embedded personnel regarding the above subject.

It is informed that the proposed concrete road have potential landslide and flooding hazards. Further, the subject area is made up of loose, unconsolidated sediments that are susceptible to erosion.

For your information and record.

RGT/EMU Doc. No. 2022-6625

FELIZARDO B. CAYATOC



July 18, 2022

MEMORANDUM

FOR : The Provincial Environment and

Natural Resources Officer

Sta Monica, Puerto Princesa City

FROM: The Community Environment and

Natural Resources Officer

Taytay, Palawan

SUBJECT: ONSITE VISIT ON THE PROPOSED CONCRETTING OF

THE BARANGAY ROAD LOCATED AT BARANGAY

DEBANGAN, TAYTAY, PALAWAN

Respectfully forwarded is the memorandum dated July 15, 2022 of Mr. Francis Jade R. Cometa, Science Research Specialist II regarding the onsite visit on the proposed concreting of the barangay road located at Barangay Debangan, Taytay, Palawan.

The inspection shows that some areas of the proposed concrete road has potential landslide and flooding hazards as observed by the hazards signages placed along the road. Additionally, the area where the road will be built is made up of loose, unconsolidated sediments that are susceptible to erosion. The risk posed by the seas during monsoon and typhoon seasons, which may compromise the integrity of the concrete road, is increased by its proximity to the coast.

In view hereof, respectfully advised that this office already sent a letter dated July 18, 2022 to the Taytay LGU regarding the results and recommendations of the said inspection.

For information and further instruction.

(Q)

JUL 19 2022

2008

Cc.

The Regional Executive Director

DENR - MIMAROPA

The Regional Director Mines and Geosciences Bureau MIMAROPA Region

MIMAROPA Region 7/F DENR Bldg., 1515 Roxas Blvd. Ermita, Manila

by the National Highway, Poblacion, Taytay, Palawan 5312 email ad: cenrotaytaypal@yahoo.com



Republic of the Philippines Department of Environment and Natural Resources

Region IV- MIMAROPA
COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE
5312 Taytay, Palawan

MEMORANDUM

FOR

The CENR Officer

Taytay, Palawan

FROM

THE UNDERSIGNED

SUBJECT

ONSITE VISIT ON THE PROPOSED CONCRETTING OF THE

BARANGAY ROAD LOCATED AT BARANGAY DEBANGAN.

TAYTAY, PALAWAN

DATE

JULY 14, 2022

Pursuant to Travel Order No. 07-2022-0879, the undersigned conducted an onsite visit on the proposed concreting of barangay road located at Bgy. Debangan, Taytay, Palawan.

Background Information

On June 07, 2022, per the request of the Taytay Municipal Planning and Development Council (MPDC), the undersigned conducted an onsite visit in the island barangay of Debangan regarding their barangay road concreting proposal.

Purpose and Scope

The purpose of the activity is to inspect the road for the proposed concreting. The activity also includes an ocular inspection of the possible source of aggregates for the said project.

Findings and Observation

- 1. The area is located at Bgy. Debangan, Taytay, Palawan. It is approximately 31 kilometers aerial distance northeast of Taytay town proper and accessible by a 2-hour boat ride from Taytay wharf. Based on the Global Positioning System (GPS) reading acquired by Timestamp Camera, the location can be defined by the following coordinates: 11°00'57.4" north latitude and 119°43'47.8" east longitude.
- 2. On June 07, 2022, the undersigned together with the representatives from Taytay MPDC and Municipal Engineering Office went to Bgy. Debangan. Upon arrival, the team immediately proceeded to the barangay hall for a courtesy call with the barangay officials. (Photo 1)
- 3. According to Bgy. Captain Rolando N. Hermoso, a 740-meter barangay road was proposed for concreting. It is from an existing barangay road that traverses the

southwestern part of the island where the majority of the island's population is located. (Annex 1)

- 4. The area where the road will be built is situated in a generally flat ground near the foot of a hill and near the shore. The concrete road will be built under unconsolidated materials mostly composed of alluvial sediments. (Photo 2)
- 5. Areas near the side of the mountain are most likely at risk of landslide. This is evident by the landslide hazard sign seen along the road. (Photo 3)
- 6. A dry creek was also observed during inspection. According to the barangay captain, the said creek only runs during the rainy seasons and sometimes overflows when rainfalls are heavy. A flood hazard sign can also be seen near the creek. (Photo 4)
- 7. After inspecting the road, the undersigned then proceeded to the area where the barangay intend to source their aggregates to be used in the construction of the barangay road.
- 8. The source area is located at the northern part of the island. It is a narrow strip of coastline characterized by sand to boulder sized sediments. (Photo 5)
- 9. The said area is also where the barangay got their aggregates from the construction of other projects previously done on the barangay.

Comments and Recommendations

- 1. Based on the field findings and observation, parts of the barangay where the road is situated are susceptible to landslide or mass wasting and flooding. Also, due to its close proximity with the shore, hazards posed by the sea (e.g. strong waves, storm surge), may also affect the integrity of the concrete road.
- 2. Since the project will be built under loose sediments, proper engineering measures are recommended to prevent the possible erosion along the concrete road. Drainages shall also be built along the road and along the creek to divert the flowing water.
- 3. Furthermore, pursuant to Batas Pambansa Blg. 265 or the *Act Prohibiting the Extraction of Gravel and Sand from Beaches*, extraction of aggregates within the area suggested by the barangay are hereby prohibited.

For CENRO's information and further actions

FRANCIS JADIE R. COMETA Science Research Specialist II Cc

The Regional Director
Mines and Geosciences Bureau
MIMAROPA Region
7/F DENR Bldg., 1515 Roxas Blvd. Emita, Manila

PHOTO DOCUMENTATION



Photo 1: The undersigned together with the officials from the MPDC paid a courtesy call with the barangay officials.




Photo 2: Photo of the barangay road.




Photo 3: A landslide prone sign observed at the area close to foot of the hill.



Photo 4: A flood prone sign erected along a dry creek.



Photo 5: A beach area at the northern part of the island where the aggregates will be extracted.

ANNEX 1



Location Map of Barangay Debangan.