



Republic of the Philippines
Department of Environment and Natural Resources

MIMAROPA Region

Provincial Environment and Natural Resources Office

Bgy. Sta. Monica, Puerto Princesa City, Palawan

E-mail: penropalawan@denr.gov.ph

Telfax No. (048) 433-5638

LDS File SINEMCR

11 January 2022

MEMORANDUM

FOR : The Regional Executive Director
MIMAROPA Region
Roxas, Blvd. Ermita, Manila


FROM : The Provincial Environment and
Natural Resources Officer

SUBJECT : **ROUGH ESTIMATED DAMAGE COST DONE BY TYPHOON
ODETTE IN SNAKE ISLAND NCMCR**

Respectfully submitting the attached rough estimate damage cost done by Typhoon Odette in Snake Island – National Coastal and Marine Center for Research with total amount of Five Million Three Hundred Seventy Thousand Pesos (Php 5,370,000.00).



The said estimate covers the damages on both watercrafts and infrastructures of Snake Island. Further, the speedboat, MBca Hawksbill and Admin Building were insured thru GSIS. Report of the damages was already forwarded to Property and Supply Unit of PENRO for processing of insurance computations/claims.

For your information and further instruction.



ERIBERTO B. SAÑOS, CESE



DENR PENRO
PALAWAN RECORDS
RELEASED

BY: 
DATE:  CN 22-40
JAN 11 2022

2022-0202



Damages	Rough Estimated Damage Cost
Speedboat	
1. The steering wheel and the boat captain's set were detached from the body	- Php 200,000.00
2. The cover hood was destroyed and remove, and the cover hood frames were misaligned	
3. The engine's cover was destroyed and missing	
4. Fortunately, the body has no damage at all	
M/Bca Kalungpang, 8 seating capacity (2.96GT) – this boat was dry-docked in Snake Island NCMCR	- Php 100,000.00
1. The body of boat was totally shattered	
2. The debris of the body were scattered in the northern part of the Admin Building and inside of the mangrove area	
M/Bca Hawksbill, 20 seating capacity (6.59GT)	- Php 900,000.00
1. The body of the boat was totally wrecked	
2. The remnants were found inside the mangrove area and some are in the northerly part of Admin Building	
3. The hull "kasko" with the engine attached found in the northern part of the island which is still submerged in the sea water	
4. The propeller and other parts were also detached from the body	
Main building	- Php 2,000,000.00
1. The front hallway was tear down and the sand inside of it were washout	
2. The part of the roof was also damage and portion of outside ceiling was detached	
3. The ceiling inside of the building (hall part) was tear down	
4. Some of front windows were scattered by strong winds	
5. There was also cracked and leaked in the other parts of the Admin Building	
Other facilities	
1. Big shed was ripped down	- Php 350,000.00
2. The comfort room near the big shed was damaged; part of the roof was removed and the foundation of the CR was emerged due to the washout of the sand	- Php 70,000.00
3. The part of the boardwalk railings was cracked and destroyed	- Php 70,000.00
4. The generator house was damaged and the roof was detached from the house; pathway was tear down	- Php 100,000.00



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
Provincial Environment and Natural Resources Office
Bgy. Sta. Monica, Puerto Princesa City, Palawan
E-mail: penropalawan@denr.gov.ph
Telfax No. (048) 433-5638

5. The dive house and comfort room was totally wrecked; the posts were cracked and damaged, the roof of the comfort room was removed and the pathway was also tear down.	- Php 1,500,000.00
6. The kitchen area has also damages; the wall detached and the floor area in the front part which served as the dining area was shattered and also the sand that helps the foundation to be stronger were washout, almost 2 feet of the post were emerged	- Php 80,000.00
Others	
1. Mangrove trees in the vicinities of the admin building are heavily damage	
2. The sand area widened from its natural form	
	Total Amount: Php 5,370,000.00

Please see the attached documentation.

For your information and further instruction.

Prepared by:

REYMART B. FUENTES

Project Monitoring and Evaluation Officer

Noted by:

RHODORA B. UBANI

Chief, CDS / SIMO