

OCT 0 2 2023

MR. JOE AMIL M. SALINO Regional Director DENR-EMB – MIMAROPA 6th Floor, DENR by the Bay Bldg., Roxas Blvd., Ermita, Manila

Subject: Report on Oil Spill Incident in the Port of Puerto Princesa on September 29, 2023

Dear Director Salino:

We respectfully submit the report detailing the oil spill incident within the Port of Puerto Princesa on September 29, 2023, in compliance with DENR Administrative Order No. 2014-02.

The incident was immediately reported and responded to by Philippine Coast Guard Maritime Environmental Protection Group (MEPGroup). The Philippine Ports Authority and the PCBSI Terminal Corporation were also actively involved in the response operation. The incident was successfully contained on the same day collecting approximately two (2) drums of spilled oil.

The investigation into the incident remains ongoing under the jurisdiction of the PCG. For your reference, we have attached the Environmental Incident Report along with photographs taken during the response operation.

Very truly yours,

ALLAN P. ABOROT

Pollution Control Officer

Noted :

ELIZALDE M. ULSON Rort Manager/ Managing Officer

Encl: as stated

PORT MANAGEMENT OFFICE – PALAWAN PPA Administrative Building, Port Area Bgy. Bagong Pag-asa, Puerto Princesa City, Palawan Tel. Nos. (048) 433-0356 / (048) 434-5626, Fax (048) 434-4881 Email address: pmopalawan@ppa.com.ph

PLW-23100222

Environmental Incident Report

	Port of Puerto Pr	incesa		
Address:	Bgy. Bagong Pag-	Bgy. Bagong Pag-asa, Puerto Princesa City, Palawan		
Name of Managing Head:	Elizalde M. Ulson	Elizalde M. Ulson		
Name of PCO:	Allan P. Aborot	Allan P. Aborot		
Date of Incident:	September 29, 20	September 29, 2023		
Time of Incident:	0715h to 1330H	0715h to 1330H		
Port of Puerto Princesa from the Ba Puerto Princesa. This sighting was p	on control device environmental media ste to environment media andards standards stant Statistician - Ranillo aywalk Area, a part of the promptly reported to the e Environmental Protectio	B. Fernandez c Coastal Park u Philippine Coa	bserved an oil spill advancing towards berth no. 18 of nder the jurisdiction of the Local Government of st Guard (PCG). Group) deployed and lowered oil spill booms and	
During the incident, PPA provided operations. Additionally, our team their request. Furthermore, a team	an area for the PCG to sto was dispatched to assist t n from the PCBSI Terminal	ore their equip he PCG in colle Corporation a	the port. ment, tools, and supplies, facilitating their response ecting absorbent pads within the oil spill boom as per ctively participated in the response operation.	
During the incident, PPA provided operations. Additionally, our team their request. Furthermore, a team <u>The incident was successfully conta</u> Estimated Amount of Chemicals,	an area for the PCG to sto was dispatched to assist t n from the PCBSI Terminal ained at approximately 13 Hazardous Wastes, Emis	ore their equip the PCG in colle Corporation a 30H. sions, and/or s of spilled oil	ment, tools, and supplies, facilitating their response ecting absorbent pads within the oil spill boom as per ctively participated in the response operation. Effluents Released to the Receiving Environment:	
During the incident, PPA provided operations. Additionally, our team their request. Furthermore, a team The incident was successfully conta Estimated Amount of Chemicals, The PCG reported the collection of Bay). The type of oil spilled is still u Probable Cause of the Incident:	an area for the PCG to sto was dispatched to assist to from the PCBSI Terminal ained at approximately 13 Hazardous Wastes, Emis approximately two drum inder investigation by the ope of the oil spilled are s	ore their equip the PCG in colle Corporation a 30H. sions, and/or s of spilled oil i PCG.	ment, tools, and supplies, facilitating their response ecting absorbent pads within the oil spill boom as per ctively participated in the response operation. Effluents Released to the Receiving Environment: n the 500-square-meter affected area (Puerto Princesa stigation by the Philippine Coast Guard MEPGroup.	
During the incident, PPA provided operations. Additionally, our team their request. Furthermore, a team The incident was successfully conta Estimated Amount of Chemicals, The PCG reported the collection of Bay). The type of oil spilled is still u Probable Cause of the Incident: The cause, the source, and the ty	an area for the PCG to sto was dispatched to assist to from the PCBSI Terminal ained at approximately 13 Hazardous Wastes, Emis approximately two drum inder investigation by the ope of the oil spilled are s	ore their equip the PCG in colle Corporation a 30H. sions, and/or s of spilled oil PCG. till under inve	ment, tools, and supplies, facilitating their response ecting absorbent pads within the oil spill boom as per ctively participated in the response operation. Effluents Released to the Receiving Environment: n the 500-square-meter affected area (Puerto Princesa stigation by the Philippine Coast Guard MEPGroup.	
During the incident, PPA provided operations. Additionally, our team their request. Furthermore, a team <u>The incident was successfully conta</u> Estimated Amount of Chemicals, The PCG reported the collection of Bay). The type of oil spilled is still u Probable Cause of the Incident: The cause, the source, and the ty Interim/Contingency Measures to	an area for the PCG to sto was dispatched to assist to from the PCBSI Terminal ained at approximately 13 Hazardous Wastes, Emis approximately two drum inder investigation by the ope of the oil spilled are s	ore their equip the PCG in colle Corporation a 30H. sions, and/or s of spilled oil PCG. till under inve	ment, tools, and supplies, facilitating their response ecting absorbent pads within the oil spill boom as per ctively participated in the response operation. Effluents Released to the Receiving Environment: n the 500-square-meter affected area (Puerto Princesa stigation by the Philippine Coast Guard MEPGroup.	

te: Corrective actions to prevent recurrence, estimated amount of the needed recovery/repair/clean up, and estimated date og completion for any needed repairs should be reflected in the next submission of the SMR.




Aerial view of the port showing the first sighting of the oil spill



Briefing of PCG, PPA, and PCBSI Terminal Corp. teams by the PCG MEPGroup





Spill booms at berths 9 and 10





Absorbent pads to captivate the oil spill



PPA personnel assisting in the retrieval of oiled absorbent pads