



Republic of the Philippines  
Department of Environment and Natural Resources  
**PENRO MARINDUQUE**

DENR-MIMAROPA RECORDS SECTION	
<b>RECEIVED</b>	
03 OCT 2022	
<input type="checkbox"/> INCOMING	<input type="checkbox"/> OUTGOING
BY: _____	DATE NO. _____

September 19, 2022

**MEMORANDUM**

**FOR :** The Regional Executive Director  
DENR, MIMAROPA Region

**THRU :** The Assistant Regional Director  
for Technical Services

**FROM :** The OIC, PENR Officer

**SUBJECT :** MAINTENANCE OF SIGNAGES, INFRASTRUCTURES AND  
FIXTURES IN PROTECTED AREA MANAGEMENT OFFICE  
(PAMO) - MARINDUQUE WILDLIFE SANCTUARY (MWS) FOR  
THE THIRD QUARTER, CY 2022.


Respectfully forwarded is the Report on the Maintenance of Signages, Infrastructures and Fixtures in Protected Area Management Office (PAMO)-Marinduque Wildlife Sanctuary (MWS) for the 3<sup>rd</sup> Quarter, CY 2022 dated September 16, 2022 together with the geotagged photos of the demarcated monuments, signages, infrastructures and fixtures listed in the tabulated forms.

For information, record and further instruction.

  
**IMELDA M. DIAZ**



Republic of the Philippines  
Department of Environment and Natural Resources  
**PENRO MARINDUQUE**



**MEMORANDUM**

**FOR : The OIC, PENR Officer**  
**Boac, Marinduque**

**THRU : The Protected Area Superintendent**  
**Marinduque Wildlife Sanctuary** *Φ*

**FROM : The Park Maintenance Foreman**

**SUBJECT : MAINTENANCE OF SIGNAGES, INFRASTRUCTURES AND**  
**FIXTURES IN MARINDUQUE WILDLIFE SANCTUARY (MWS) AS OF**  
**3<sup>rd</sup> QUARTER, CY 2022.**

In connection to the target of Protected Area Management Office (PAMO) under Protected Areas Development and Management/ Ecotourism Development/ Maintenance of Signages/ Billboards Management, please be informed that 18 concrete signages, 408 corner/ monuments and 283 newly installed signages within MWS boundaries and strategic places have been continuously maintained and protected including existing infrastructures, furnitures and fixtures in MWS as of 3<sup>rd</sup> Quarter of Calendar Year 2022.

Be informed further that the maintenance and protection of the signages and infrastructure are regularly undertaken with the assistance of 8 Park Rangers, 6 Biodiversity Protection Assistants, 2 Forest Protection Officers, 1 Tourism Aide and 1 PAM Office Caretaker/Utility. Please find attached tabulated detailed information of said activities and geotagged photos for further reference.

For information, record and further instruction.

*Roderick S. Villanueva*  
**RODERICK S. VILLANUEVA**



Particulars	Location	Qty.	Total Cost (Php)	Date of Completion	Maintenance Work Conducted	Remarks
<b>A. Signages</b>						
<b>A.1 Concrete</b> Along the National Road at Barangays	1) Daykitin Buenavista	2	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	2) Malbog, Buenavista	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	3) Malibago, Torrijos	2	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	4) Poblacion, Torrijos	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	5) Taytay, Sta. Cruz	2	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	6) Tumagabok, Boac	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	7) Sih, Buenavista	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
Along the perimeter boundary of the Marinduque Wildlife Sanctuary at Barangays	1) Bagtingon, Buenavista	2	11,000.00	2017	Repaired/ Repainted	monitored/ maintained
	2) Malbog, Buenavista	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	3) Tumagabok, Boac	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	4) Tambunan, Boac	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	5) Canat Boac	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	6) Malibago, Torrijos	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	7) Sibuyao, Torrijos	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
<b>A.2 Newly Installed MWS Concrete Signages</b>	23 Barangays of MWS	283		2022	Newly installed	Newly installed
<b>A.2 Wood</b>	1) PAMO Ecotourism Satellite Office, PENRO Compound	1	3,200.00	2017	Repaired/ Repainted	maintained
	2) PAMO Information Board	1	3,200.00	2017	Repaired/ Repainted	maintained
	3) Ecotourism Information Center - PAMO Tumagabok, Boac	1	3,200.00	2017	Repaired/ Repainted	maintained
<b>A.3 Tarpaulin</b>	Rate of fees and rules and regulations in ecotourism PAMO Tumagabok, Boac.	3	2,800.00	2018		maintained
<b>A.4 Concrete Monuments</b>	Demarcated Boundaries of MWS (Parcel 1 and 2)	408		2020-2022	Newly installed	monitored/ maintained
<b>B. Infrastructure/ Buildings</b>						
<b>B.1 Ecotourism Information Center</b>	PAMO Tumagabok, Boac	1	200,000.00	2016	Renovated/ Repainted Corrugated Sheets to Color Roof Wood Trusses to Steel trusses	maintained



Particulars	Location	Qty.	Total Cost (Php)	Date of Completion	Maintenance Work Conducted	Remarks
<b>A. Signages</b>						
<b>A.1 Concrete</b> Along the National Road at Barangays	1) Daykitin Buenavista	2	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	2) Malbog, Buenavista	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	3) Malibago, Torrijos	2	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	4) Poblacion, Torrijos	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	5) Taytay, Sta. Cruz	2	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	6) Tumagabok, Boac	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	7) Sihí, Buenavista	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
Along the perimeter boundary of the Marinduque Wildlife Sanctuary at Barangays	1) Bagtingon, Buenavista	2	11,000.00	2017	Repaired/ Repainted	monitored/ maintained
	2) Malbog, Buenavista	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	3) Tumagabok, Boac	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	4) Tambunan, Boac	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	5) Canat Boac	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	6) Malibago, Torrijos	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	7) Sibuyao, Torrijos	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
<b>A.2 Newly Installed MWS Concrete Signages</b>	23 Barangays of MWS	283		2022	Newly installed	Newly installed
<b>A.2 Wood</b>	1) PAMO Ecotourism Satellite Office, PENRO Compound	1	3,200.00	2017	Repaired/ Repainted	maintained
	2) PAMO Information Board	1	3,200.00	2017	Repaired/ Repainted	maintained
	3) Ecotourism Information Center - PAMO Tumagabok, Boac	1	3,200.00	2017	Repaired/ Repainted	maintained
<b>A.3 Tarpaulin</b>	Rate of fees and rules and regulations in ecotourism PAMO Tumagabok, Boac.	3	2,800.00	2018		maintained
<b>A.4 Concrete Monuments</b>	Demarcated Boundaries of MWS (Parcel 1 and 2)	408		2020-2022	Newly installed	monitored/ maintained
<b>B. Infrastructure/ Buildings</b>						
<b>B.1 Ecotourism Information Center</b>	PAMO Tumagabok, Boac	1	200,000.00	2016	Renovated/ Repainted Corrugated Sheets to Color Roof Wood Trusses to Steel trusses	maintained



<b>B.2 PAMO with 2.5 KW Solar Panel Energy</b>	PAMO Tumagabok, Boac	1	1,620,000.00	2016	For repair/ Replacement of various parts (Solar Panel)	Solar Panel has been damaged by typhoon (thunder/ lightning) Affected parts were battery, inverter and controller
<b>B.3 PAMO Ecotourism Information Satellite Office</b>	PENRO Compound, Boac	1	50,000.00	2018	-Repaired/ Improved -Rough Cement Floor to Floor Tiles -Floor Area has been extended	monitored/ maintained
<b>B.4 Multi Purpose Building with 530 watts Solar Panel</b>	PAMO Tumagabok, Boac	1	800,000.00	2018	-For repair/ Replacement of various parts (Solar Panel)	Solar Panel has been damaged by typhoon, (thunder/ lightning) Affected parts were batteries, inverter and controller.
<b>C. Water System</b>	Water System for PAMO, Ecotourism Center and Multi- Purpose Hall at Tumagabok, Boac	1	75,000.00	2017	Maintenance of Cleanliness and installation of water pipe lines.	monitored/ maintained
<b>D. View deck</b>	1. Tumagabok, Boac	1	2016	150,000.00	- Renovated - Maintenance of cleanliness in the surroundings. -From light materials to steel concrete/materials	monitored/ maintained
	2. Mt. Natilus, Bagtingon, Buenavista	1	2016	120,000.00	-Damaged by typhoon in 2019.	For repair
<b>E. Ranger Station</b>	1. Balagbag Mountain Range, Malibago, Torrijos	1	2018	110,000.00	-Repaired - Maintenance of cleanliness in the surroundings. Grasscutter was used in cleaning.	monitored/ maintained
	2. Mt. Natilus, Bagtingon, Buenavista	1	2016	60,000.00	-Damaged by typhoon in 2019.	For repair
<b>E. Registration booth</b>	PAMO Tumagabok, Boac	1	2018	70,000.00	-Repainted	maintained
<b>F. Additional Kitchen</b>	PAMO Tumagabok, Boac	2	2017	150,000.00	-Repainted	maintained
<b>G. Parking shed</b>	PENRO Compound, Boac	1	2016	200,000.00	-Maintenance of cleanliness	maintained
<b>H. Outdoor Comfort rooms</b>	PAMO Tumagabok, Boac	1	2018	150,000.00	-Maintenance of cleanliness	maintained
<b>I. Vegetation plot</b>	PAMO Tumagabok, Boac	2 has.	2017	70,000.00	-Maintenance of cleanliness	monitored/ maintained
<b>J. Concrete Picnic Table</b>	PAMO Tumagabok, Boac	5 has.	2018	35,000.00	-Maintenance of cleanliness	maintained
<b>K. Concrete Steps</b>	PAMO Tumagabok, Boac	289	2017	30,000.00	-Maintenance of cleanliness	maintained




		steps				
<i>L. Eco Trail</i>	PAMO Tumagabok, Boac	1.5 kms.	2017	25,000.00	-Maintenance of cleanliness	maintained
<i>M. Wooden Furnitures and Fixtures</i>			2017-2018			
<i>M.1 Tables</i>			2017-2018			
<i>M.1.1. Office Tables</i>	PAMO Tumagabok, Boac PAMO Satellite Office Boac	22 6	2018 2018		Revarnished Revarnished	maintained maintained
<i>M.1.2. Kitchen Table</i>	PAMO Tumagabok, Boac	2	2018		Revarnished	maintained
<i>M.1.3. TV Table</i>	PAMO Tumagabok, Boac	2	2018		Revarnished	maintained
<i>M.1.4. Information Table</i>	PAMO Tumagabok, Boac	1	2018		Revarnished	maintained
<i>M.1.5. Long Table</i>	PAMO Satellite Office Boac	2	2018		Revarnished	maintained
<i>M.1.6. Computer Table (for 3 PC)</i>	PAMO Satellite Office Boac	1	2018		Revarnished	maintained
<i>M.1.7. Benches without backrest</i>	PAMO Tumagabok, Boac	5	2018		Revarnished	maintained
<i>M.1.8. Benches with Backrest</i>	Brgy. Tumagabok, Boac PAMO Satellite Office Boac	14 2	2018 2018		Revarnished Revarnished	maintained maintained
<i>M.1.9. Suggestion Box</i>	PAMO Tumagabok, Boac	1	2018		Revarnished	maintained
<i>M.1.10 Buttrass Bench/ Chair</i>	PAMO Tumagabok, Boac	2	2018		Revarnished	maintained
<i>M.1.11. Rostum</i>	PAMO Tumagabok, Boac	1	2018		Revarnished	maintained
<i>M.1.11. Office Chairs</i>	PAMO Tumagabok, Boac PAMO Satellite Office Boac	38 12	2018 2018		Revarnished Revarnished	maintained maintained
<i>M.1.12. Kitchen Chairs</i>	PAMO Tumagabok, Boac	3	2018		Revarnished	maintained
<i>M.1.13. Bookshelf</i>	PAMO Satellite Office Boac	1	2018		Revarnished	maintained

Prepared by:

  
**RODERICK S. VILLANUEVA**  
 Park Maintenance Foreman

Checked/Verified by:

  
**EMETERIO M. RECTO**  
 SEMS/PASu

Noted by:

**IMELDA M. DIAZ**  
 OIC – PENR Officer



## CONCRETE SIGNAGES



Brgy. Taytay, Sta. Cruz



Brgy. Daykitin, Buenavista

4

4





Malbog, Buenavista



Brgy. Malibago, Torrijos



Brgy. Sihi, Buenavista



Brgy. Malibago, Torrijos

7 f





Brgy. Binunga, Boac



Brgy. Antipolo, Gasan



Brgy. Nangka, Torrijos




Brgy. Tambangan Sta. Cruz

4

7





Brgy. Tumagabok, Boac



Brgy. Boi, Boac



Brgy. Bagtingon, Buenavista



Brgy. Makulapnit, Sta. Cruz


4

7







Brgy. Poblacion, Torrijos



Brgy. Masalukot, Sta. Cruz



Brgy. Malbog, Buenavista (Haynon)




Brgy. Malibago, Torrijos

4




## NEWLY INSTALLED MWS CONCRETE SIGNAGES



F





↑

4






4

4







TH





TH





9 4







4

7







4

4



## WOOD SIGNAGES




4

4







# TARPAULIN








# CONCRETE MONUMENTS



4





4


4





9





4 7







4

4









4

4









7

4






Handwritten marks: a small 'x' and a stylized signature or mark.




## PAMO ECOTOURISM INFORMATION CENTER



46



## PROTECTED AREA MANAGEMENT OFFICE



f



## SOLAR PANEL




of

f



## PAMO SATELLITE OFFICE



7

7



## RANGER STATION




Brgy. Bagtingon, Buenavista ( Mt. Natilus)

7

4



## Multi Purpose Building with 530 watts Solar Panel



Handwritten signature or initials.



## WATER SYSTEM



4

4



## VIEW DECK





4

4



## RANGER STATION



Brgy. Malibago, Torrijos

4



## REGISTRATION BOOTH



T

4



## ADDITIONAL KITCHEN



9

uf



## PARKING SHED




6

4




## OUTDOOR COMFORT ROOM





## VEGETATION PLOT





7

4



## CONCRETE PICNIC TABLE




9

4





# CONCRETE STEPS



4



# ECO TRAIL



P

4







## FURNITURE AND FIXTURE



9

4









7

4






4

f





+

+






7

4





+

f