

June 06, 2023

MEMORANDUM

FOR

: The Regional Executive Director

DENR MIMAROPA Region

THRU

The Assistant Regional Director for Technical Services

ATTENTION

The OIC-Chief, Surveys and Mapping Division

FROM

The OIC-PENR Officer

SUBJECT

: REQUEST FOR AMENDMENT/CORRECTION OF

ERRONEOUS LOT DATA COMPUTATION SITUATED IN

BARANGAY MARANLIG, TORRIJOS, MARINDUQUE

This pertains to the application for Special Free Patent of BLGU-Maranlig, Torrijos, Marinduque, as represented by P/B Meneleo P. Regalado over a parcel of land (Evacuation Center) identified as Lot No. 3110, Cad 612-D situated in Barangay Maranlig, Torrijos, Marinduque.

Upon plotting of the available technical description of the aforesaid lot, it was found out that along line 2-3 with a bearing of N 16° 09' E, 33.67 meters and along line 3-4 with a bearing of S 15° 33' E, 4.89 meters are erroneous, As a result, the corner 3 of said lot falls within the road. Likewise, the lot data computation/technical description of the aforementioned lot does not conform to the shape of the polygon in the cadastral map.

In this regard, we respectfully request for the amendment/correction of the lot data computation/technical description of the said lot for us to process/approve the application for land title of LGU of Maranlig, Torrijos, Marinduque, represented by Punong Barangay Meneleo P. Regalado.


For your consideration.

"For and in the absence of the PENRO"


SIMEON R. DIAZ

Chief, RPS/ Land Management Officer III In-Charge, Office of the PENRO

Website: https://penromarinduque.gov.ph
Email: penromarinduque@denr.gov.ph



TORRIJOS






Republic — ne Philippines Department of Environment and Natural Resources PENRO Marinduque

Application No.						Survey No.	Cad. 6	12-D		Case No.	1	5		
Applicant			Bara	ngay (Gover	nment of Mara	nlig - Evacuation Site	Lot No.	3110					
Surveyed for		Mar	indu	que	Social Hall		Location	Maran	ig, T	, Torrijos, Marinduque				
Surveyed by		Nor	bert	о Н. I	Habla		Cadastr	al Map No		13/29 N, 121/51 E				
Surveyed on		Mar	ch -	June	, 1979		T.D. App	roved on		December 19, 1980				
Tie line	N	43	-	44	W	3510.40	From BLLM # 1	Area			227		Sq. M.	
													_	

TECHNICAL DESCRIPTION

LINE	BEARING			DISTANCE	RECOMPUTATION		LINE	BEARIN		NG.	IG DISTANCE		RECOMPUTATION				
LINE		DL	MINI	40		DISTANCE	LAT	DEP	LIIVE	BEAKIN		10	DISTANCE		LAT	DEP	
1-2	S	70	-	18	W	16.41	-5.53	-15.45	11-12								
2 - 3	N	16	-	09	E	33.67	32.34	9.36	12-13								
3 - 4	S	15	-	33	E	4.89	-4.71	1.31	13-14								
4 - 5	S	12	-	12	E	22.61	-22.10	4.78	14-15								
5 - 6									15-16								
6 - 7									16-17								
7 - 8									17-18								
8 - 9							32.34	15.45	18-19								
9 -10							-32.34	-15.45	19-20								
10 -11							0.00	0.00	20-21								



CERTIFIED CORRECT:

ENGR. CYNTHIA U. LOZANO

Chief, Technical Services Division

T.D. research by:		Date:	
T.D. sketched by:		Date:	
T.D. checked by:		Date:	
Recomputed by:		Date:	
I E No	Date Issued	II o	ssued by:

LOT DATA COMPUTATION

INSTRUCTIONS:

- 1. Enter required data in the yellow colored cells.
- 2. Compare declared area with computed area for error checking.

Lot No.	=	3110
Owner	=	Marinduque Social Hall
Cad Survey No.	=	CAD 612 D C-15
CM Quadrangle	=	13, 20 N / 122, 03 E
Barrio	=	Maranlig
Mun / City	=	Torrijos
Province	=	Marinduque
Island	=	Marinduque
Geodetic Engr.	=	Not Listed
Date Surveyed	=	
Surv. Sym. & No.	=	0
L.R.C. No.	=	0
Declared Area	=	227.16

TIE POINT DATA:

BLLM 1 =	1,473,388.000	N
	617,469.380	E

NO.OF CORNERS:

4

ERROR CHECKING:

DOUBLE AREA	454.33
AREA	227.1647

ACCURACY STANDARDS:

L.E.C.	0.005233345
R.E.C.	14,824
ACC	1:15000

STATIONS -	COORDIN	NATES	TECHNICAL DESCRIPTION							
STATIONS	NORTHINGS	EASTINGS	DISTANCES	BEARINGS						
	ERROR CHECK		77.58	N/S	DEG	MIN	E/W			
BLLM 1	1,473,388.000	617,469.380	3510.40	N	43	44	W			
1	1,475,924.650	615,042.790	16.41	S	70	18	W			
2	1,475,919.120	615,027.340	33.67	N	16	09	E			
3	1,475,951.460	615,036.700	4.89	S	15	33	E			
4	1,475,946.750	615,038.010	22.61	S	12	12	E			