



December 21, 2021

MEMORANDUM

FOR : The Provincial Environment and Natural Resources Officer
Sta. Monica, Puerto Princesa City

FROM : The Community Environment and Natural Resources Officer
Taytay, Palawan

SUBJECT : **UPDATES ON THE DAMAGES CAUSED BY TYPHOON ODETTE (RAI) ON THE DENR FACILITIES WITHIN THIS JURISDICTION AS OF DECEMBER 21, 2021**

**DENR CENRO
TAYTAY, PALAWAN
RELEASED**

DATE: **DEC 22 2021** CH **3191**

Respectfully forwarded is the report of ECOMS II and DRMC team member Carolyn A. Esmenda regarding the aforementioned subject. Please be informed that Typhoon Odette (Rai) hit Taytay and El Nido municipalities on the morning of December 17, 2021 (Friday). El Nido felt the strong winds as early as 7:00 O'clock in the morning cutting electric power supply and heavy rain downpour at about 3:00 pm until 7:00 in the evening. On the other hand, heavy rain downpoured in Taytay at about 9:30 am and strong winds battered the town from about 11:00 am and until around 10:00 in the evening. The strong winds felled trees that damaged houses and other structures and rendered roads unpassable by vehicles and felled down electrical posts cutting electric power supply and cutting off communications including internet.

On December 18, 2021, there were only scattered rainshowers, strong winds had ceased and the havoc became evident. The Municipal Government of Taytay and El Nido had already mobilized its forces to clear the road and extend necessary assistance to the affected constituents. Due to the crisis at hand, the four (4) of the operational confiscated chainsaws were made available for use of the LGU-Taytay, PALECO and Rescue 165 for the abovementioned purposes.

As of date, an ongoing inventory of trees fallen along the road is now being conducted by our personnel including an assessment of the National Greening Program (NGP) and Community Based Forest Management (CBFM) project affected by the typhoon.

The following are the reported damages to DENR facilities and structures in Taytay and El Nido municipalities:

Facilities / Structures	Damages	Remarks
CENRO Taytay Office in Poblacion, Taytay, Palawan	• Glass pane at the front door broken; • Gutter at the front partially damaged; and, • Office was flooded.	Annex B

Annex A

Table 1: List of affected personnel with their corresponding damaged properties.


No.	Name of Employee	Location	Damaged Property	Remarks
1	Abus, Jao	Corong-corong, El Nido	House	Job Order
2	Adon, Edjhay H.	Tumarbong, Roxas	Roof	Job Order
3	Alvillar, Maian P.	Poblacion, Taytay	Roof	Job Order
4	Armenia, Rieben	New Guinlo, Taytay	House	Job Order
5	Asuncion, Jordan Paul	Bgy. 2, Roxas	House	Job Order
6	Badao, Angelina L.	Poblacion, Taytay	Roof and boat	Permanent
7	Balerite, Jayvee	Poblacion, Taytay	House	Job Order
8	Balvin, Erwin C.	New Guinlo, Taytay	Roof	Job Order
9	Barcoma, Belly	Liminangcong, Taytay	House	Job Order
10	Becera, Allan Jay	New Guinlo, Taytay	Roof	Job Order
11	Bose, Francis Abe	New Guinlo, Taytay	Canteen	Permanent
12	Buncag, Ruvic	Poblacion, Taytay	Roof	Job Order
13	Cacacha, Ryan J.	Mabini, El Nido	House	Job Order
14	Cagas, Raul	Bucana, El Nido	Roof; hut	Job Order
15	Cantonjos, Froilan	Poblacion, Taytay	House	Job Order
16	Conda, Reynaldo	New Guinlo, Taytay	House	Job Order
17	Dalabajan, Rocky	Old Guinlo, Taytay	House	Job Order
18	Daquer, Maureen D.	Aberawan, El Nido	Fence, wall	Job Order
19	Dela Cruz, Rose P.	Poblacion, Taytay	Roof and fence	Permanent
20	Dela Rosa, Canette O.	Poblacion, Taytay	Roof	Permanent
21	Dela Torre, Patchito	Bebeladan, El Nido	Roof	Job Order
22	Delos Santos, Sandy	Poblacion, Taytay	House	Job Order
23	Dreo, Rushean	Corong-corong, El Nido	Kitchen	Job Order
24	Gabayán, Henry	New Ibajay, El Nido	Kitchen	Job Order
25	Igam, Rico G.	Mabini, El Nido	House	Job Order
26	Jongay, Glaiza M.	Manlag, El Nido	Wall	Job Order
27	Juan, Romnick A.	Bagong-Bayan, El Nido	House	Job Order
28	Ladao, Norrien John E.	Bgy 3, Roxas	House	Job Order
29	Monterde, Jaquilyn	Masagana, El Nido	Kitchen	Job Order
30	Oab, Melky P.	Poblacion, Taytay	Roof	Job Order
31	Obrique, Precy M.	Abongan, Taytay	House	Permanent
32	Ortega, Reynold N.	Poblacion, Taytay	Partially affected Roof and wall	Job Order
33	Paulo, Marlon	New Guinlo, Taytay	House	Job Order
34	Pineda, Norie D.	Poblacion, Taytay	Roof	Permanent
35	Reño, Charlie	Poblacion, Taytay	House	Job Order
36	Rey, Lanie Jane A.	Biton, Taytay	House 1 - Roof; House 2 - totally wrecked	Permanent
37	Ricare, Redamie D.	Poblacion, Taytay	Roof	Job Order
38	Rivera, Rexander	Poblacion, Taytay	House	Job Order
39	Sebonga, Jodith A.	Aberawan, El Nido	Roof	Job Order
40	Tacob, Jerremiel S.	Tumarbong, Roxas	Poultry	Job Order
41	Tenolite, Rennie	New Guinlo, Taytay	House	Job Order
42	Tina, Francis Joy	Poblacion, Taytay	House	Job Order
43	Vasquez, Deogracias	Poblacion, Taytay	House	Permanent
44	Villanueva, Jovan P.	Maligaya, El Nido	Comfort Room	Job Order

Divers House in Bgy. Corong-corong, El Nido, Palawan	• Two service boats were partially damaged.	Recovered two kayaks being used by lagoon marshals
Visitors' Center in Bgy. Pancol, Taytay, Palawan	• None	Photos taken/shared by FR John Vincent Sanchez on 143714H December 2021 (see Annex I)

Attached are the consolidated list of affected personnel by the typhoon with their corresponding damaged properties (**Annex A**), and the photos of the abovementioned damages within Taytay and El Nido, Palawan.

For information and further instruction.

For and in the absence of the CENRO


ALEXANDER E. MANCIO
 SEMS/Chief, RPS
 In-charge, Office of the CENRO

Annex I



Situation of Visitors' Center in Bgy. Pancol, Taytay, Palawan; No Damage



