



Republic of the Philippines  
**Department of Environment and Natural Resources**  
**Region IV- MIMAROPA**  
**COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE**  
Barangay III (Poblacion), Roxas, Palawan  
Contact No. 09171606578 / 09175028647  
Email address: [cenroroxaspalawan@denr.gov.ph](mailto:cenroroxaspalawan@denr.gov.ph)

---

December 21, 2021

**MEMORANDUM**

**FOR** : The Regional Executive Director

**THRU** : The Provincial Environment and  
Natural Resources Officer


**FROM** : The OIC-Community Environment and Natural  
Resources Officer

**SUBJECT** : **UPDATE ON THE EFFECT OF SUPER TYPHOON ODETTE (RAI)**

Submitted is the update on the effect of super typhoon Odette within the area of jurisdiction (AOR) of CENRO Roxas, Palawan.

Attached is the tabulated damages of office and employees properties and equipment's.

For your information.

  
**RONIE B. GANDEZA**

# OFFICE BUILDING DAMAGES

CENRO Roxas, Palawan

OFFICE/LOCATION	CASUALTY	DAMAGE	ADVISORIES	DISASTER	REMARKS
CENRO ROXAS, PALAWAN *Bgy. III, Roxas, Palawan	None	Client shed	EO. No.087 s. of 2021 (PPDRMO)	Super typhoon "Odette"	Estimated Amount Php. 30,000.00 Totally Damaged
		Platform water tank	Memorandum Order No. 066 S. of 2021 (Municipality of Roxas)		Estimated Amount Php. 100,000.00
		Guard Post	Advisory dated December 17, 2021 issued by PENRO Palawan		Estimated Amount Php. 30,000.00 Totally damaged
		Records Building			Estimated Amount Php. 250,000.00
		Lumber shed			Estimated Amount Php. 150,000.00 Totally Damaged
		Office Building (New)			Estimated Amount Php. 1,500,000.00 Partially damaged (roofing, electrical, ceiling)
		Office Building (Old)			Estimated Amount Php. 800,000.00 Partially damaged (roofing, electrical, ceiling)
		Generator shed/ Powerhouse			Estimated Amount Php. 100,000.00 Totally damaged (roofing, electrical)
		Perimeter fence including Entrance gate			Estimated Amount Php. 100,000.00 Partially damaged

fb



		Office Equipment			Estimated Amount Php. 500,000.00 Partially damaged
		<ul style="list-style-type: none"> <li>* Wifi Connection</li> <li>* 3 Units Aircon</li> <li>* Genset Battery</li> <li>* CCTV Connection</li> <li>* 1 Photocopier</li> <li>* 5 UPS</li> <li>* 1 Scanner</li> </ul>			

# EMPLOYEES PROPERTIES DAMAGES

CENRO Roxas, Palawan

NAME OF PERSONNEL	CASUALTY	DAMAGE	ADVISORIES	DISASTER	REMARKS
Most of personnel houses are partially damaged and no casualty.					

7



**TOP VIEW OF NEW BUILDING**



**TOP VIEW OF OLD BUILDING**



**TOP VIEW OF LUMBER & CLIENT SHED, AND GUARD POST**





## PLATFORM WATERTANK









## GUARD POST AND CLIENT SHED









## PERIMETER FENCE INCLUDING ENTRANCE GATE









## LUMBER SHED OF CENRO ROXAS PALAWAN

















## GENERATOR SHED/POWERHOUSE





**RECORDS BUILDING**

















**CENRO ROXAS OLD BUILDING**









## CENRO ROXAS NEW BUILDING





