

BARANGAY BUILDINGS AND FACILITIES DAMAGE ASSESSMENT

BARANGAY	FACILITY/ BUILDING	DESCRIPTION	DAMAGED CATEGORY	PROJECT COST
		Gutter replacement		
Babuyan	Covered Gym	and repair of ceiling.	1	500,000.00
Bahile	Covered Gym		10	5,000,000.00
	Barangay Hall		1	500,000.00
Cabayugan	Covered Gym		1	500,000.00
	Barangay Hall		1	500,000.00
	Senior Citizens			
	Building		1	500,000.00
	Other Facilities		1	
Inagawan	(Satellite Clinic)	NO DAMAGE	1	500,000.00
Inagawan Kamuning	Covered Gym Covered Gym	NO DAMAGE		
Langogan	Covered Gym	Replacement of roof	1	500,000.00
Langogan				300,000.00
		Replacement of		
		ceiling, roof and		
	Barangay Hall	gutter	1	500,000.00
	Other Facilities	Replacement of roof	1	500,000.00
		Devices and the first first		
		Replacement of roof		
		and electrical fixtures and rewire for		
Luchuan	Covered Gym		3	150,000,00
Lucbuan	Covered Gym	lightings.	3	150,000.00

Luzviminda Macarascas	Other Facilities (Health Center, Waiting Area) Covered Gym Covered Gym	Replacement of roof and ceiling NO DAMAGE Replacement of roof.	3	1,500,000.00
	Barangay Hall	Replacement of gutter and ceiling	2	1,000,000.00
Manalo	Covered Gym	Replacement of roof and electrical fixtures and rewire for lightings.	3	1,500,000.00
	Derengen Hell	Replacement and repair of ceiling and electrical fixtures for	1	500.000.00
	Barangay Hall Other Facilities (Stage & Tanod Outpost)	lightings. Replacement of roof and electrical fixtures and rewire for lightings.	1	500,000.00
Mangingisda	Covered Gym Barangay Hall	Repair of roof and gut Replacement of roof a	1	500,000.00 500,000.00
	Other Facilities (Multi-purpose Hall)	Replacement of ceiling and gutter repair.	1	500,000.00

<u> </u>	1		
	Replacement of roof		
Barangay Hall		1	500,000.00
Durunguy nun			500,000.00
Other Facilities	Replacement of roof	1	500,000.00
			,
Covered Gym		1	500,000.00
, ,	•		
Covered Gym	flusher and roof.	1	500,000.00
	Replacement of		
	purlins, roofing,		
Other Facilities	trusses and ridgeroll.	1	500,000.00
	Replacement of roof		
	and electrical		
Covered Gym	fixtures.	2	1,000,000.00
Barangay Hall		1	500,000.00
Covered Gym	NO DAMAGE		
(MRF)	Repair of roof.	1	500,000.00
Covered Gym	Flashing and gutter	1	500,000.00
. ,		1	500,000.00
	No Damage		
			500 000 00
Center)		1	500,000.00
Causera d. Curra		1	500 000 00
Covered Gym	lightings.	1	500,000.00
Other Facilities			
	Replacement of coiling	1	500,000.00
			2,000,000.00
	Replacement of	4	2,000,000.00
	electrical re-wiring		
	Other Facilities Covered Gym Barangay Hall	Other FacilitiesReplacement of roof Repair of roof and gutter.Covered GymReplacement of flusher and roof.Covered GymReplacement of purlins, roofing, trusses and ridgeroll.Other FacilitiesReplacement of roof and electrical 	Barangay Halltrusses and ceiling1Other FacilitiesReplacement of roof1Covered Gymgutter.1Replacement of flusher and roof.1Covered GymReplacement of purlins, roofing, trusses and ridgeroll.1Other FacilitiesReplacement of roof and electrical fixtures.1Covered GymReplacement of roof and electrical fixtures.1Covered GymNO DAMAGE1Other FacilitiesReplacement of roof, and electrical fixtures.1Covered GymNO DAMAGE1Covered GymNO DAMAGE1Covered GymReplacement of roof, and electrical fixtures.1Covered GymNo DAMAGE1Covered GymReplacement of roof, Flashing and gutter1Covered GymReplacement of roof, flashing and gutter1Covered GymNo Damage1Covered GymReplacement of roof, and electrical fixtures and rewire for and electrical fixtures and rewire for1Covered GymIightings.1Covered GymReplacement of ceiling and rewire for and electrical fixtures and rewire for and rewire for1Covered GymReplacement of ceiling and rewire for and rewire for

		Replacement of		
		roof,gutter and		
		ridgeroll and minor re-		
Sicsican	Covered Gym	wiring works.	1	500,000.00

TOTAL PHP

27,150,000.00