

SPPF COMMUNICATION/TACTICAL OPERATIONS SECTION MESSAGE SLIP			
			DATE: 09-09-22
NAME OF SENDER: Col cathryn Joy C Antonio			
DESIGNATION: Admin Officer			
MESSAGE RECEPIENT: Mr. ANASTACIO A. SANTOS CENRO, DENR NIMAROPA Region			
TYPE OF MESSAGE: ☒ EMAIL ☐ SMS MESSAGES ☐ THRU RADIO			
PURPOSE OF MESSAGE: Request for Assistance			
MESSAGE TO BE SEND OR TRANSMITTED:			
Report on fallen timber at Aruyan Falls, SPPF. Request for inspection/verification and permit to utilize it.			
Agustino Col CATHRYN JOY C ANTONIO SIGNATURE OVER PRINTED NAME			



Republic of the Philippines
Department of Justice
BUREAU OF CORRECTIONS
SABLAYAN PRISON AND PENAL FARM
Sablayan, Occidental Mindoro



08 September 2022

Mr. ANASTACIO A SANTOS
CENR Officer
DENR MIMAROPA Region
Sto. Niño, Sablayan, Occidental Mindoro

Dear Mr. Santos:

Greetings!

This is to report to your Office, about the fallen timber situated at the Aruyan Falls, AOR of SPPF, said timber collapsed into the roofing of our Water System Tank, we wish to take out the same, fearing that it may further damage the Tank, photos attached herewith.

In this regards, we are requesting from your Forest Protection and Conservation Team for inspection/ verification of said fallen timber, and further request for the issuance of permit to utilize it for Institutional Projects of this Bureau, to support our construction projects

Hoping this request merits your consideration, generous approval and prompt action on this matter.

For any inquiries, you may reach our Office at email address opcensppf@gmail.com.

Thank you and more power!


CTSUPT JOSE B VERDADERO JR
Officer-In-Charge

Copy furnished:

- 1 - Admin
- 1 - OpCen
- 1 - Supt.'s Office

JBVJr/Jrg

LE-152 s. 2022 - Admin Files 2022/ Letter

"Reforming Lives, Community Thrives"



BUREAU OF CORRECTIONS
SABLAYAN PRISON AND PENAL FARM
BRGY MALISBONG, 5104 SABLAYAN
Occidental Mindoro
GENERAL SERVICES SECTION



FOR : CCINSP JOEL M ARNOLD
Acting Superintendent, SPPF

SUBJECT : REQUEST FOR ASSISTANCE FOR DISLODING OF LOG AT
WATER SYSTEM RESERVOIR ROOF


DATE : 6 SEPTEMBER 2022

1. Reference:
 - a. Situation report dated 5 September 2022, signed by CO3 Augusto E Sicnao, Office In-Charge of Water System Unit.
 - b. See attached document.
2. Hence, we respectfully request for assistance to properly extricate the log in accordance to DENR rules and regulations and to avoid further damage to the infrastructures roofing.
3. Furthermore, repair of damaged roof will follow immediately after extraction.
4. For information and URGENT facilitation.

CSINSP FRANCISCO A MADRID
Chief, General Services Section

"Reforming Lives, Community Thrives"

CO3 AGUSTO E SICNAO
Water System In-Charge



1. Scheduled regular maintenance and repair conducted at Aruyan Falls, 0900H 5 September 2022.
2. Upon inspection, it has been found that the Water System Tank Roof was damaged, due to the impact brought by collapsed tree.
3. Attempt to dislodge the tree to avoid further damage to the roof was not possible, due to the enormous size that may require additional workforce and mechanical help.
4. With this, we are requesting the use of chainsaw and additional workforce to remove the said log.
5. Furthermore, repair of the Water System Tank Roof will follow immediately
6. For information and guidance.

FOR : CSINSP FRANCISCO A MADRID
Chief, General Services Section
SUBJECT : SITUATION REPORT ON WATER SYSTEM TANK
DATE : 5 SEPTEMBER 2022

BUREAU OF CORRECTIONS
SABLAYAN PRISON AND PENAL FARM
BRGY MALISBONG, 5104 SABLAYAN
Occidental Mindoro
GENERAL SERVICES SECTION





