



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE
Bgy. Poblacion 5, Coron, Palawan
Contact No. 09175042633
Email Address: cenrocoron@denr.gov.ph

July 26, 2023

MEMORANDUM

FOR : The Regional Executive Director
DENR - MIMAROPA Region
1515 DENR By the Bay Building, Roxas Blvd.
Barangay 668 Ermita, Manila

THRU : The PENR Officer
Barangay Sta. Monica
Puerto Princesa City, Palawan

FROM : The OIC, Community Environment and
Natural Resources Officer

SUBJECT : **REPORT ON THE CONDUCTED MONITORING AFTER
THE INCEPTION OF TYPHOON EGAY**

Please be informed that on July 26, 2023, this office led by the undersigned have coordinated with the Local Government within our area of jurisdiction and conducted monitoring after the inception of Super Typhoon Egay (Doksuri). Although no storm warning signal raised in Calamianes Islands, heavy rainfall and strong winds brought by south-west monsoon was experienced intensified by super typhoon Egay which resulted to floods in low-lying/flood-prone areas within our area of jurisdiction.

As per coordination with the Local Government Units, some barangays have experienced moderate winds and rainfall however, no floods have been observed within the area of jurisdiction. In the municipality of Coron, a simultaneous cleaning and clearing operation was undertaken in the affected areas. A highwater level and strong current was observed in the rivers particularly in Labangan river located at Barangay Guadalupe, residential houses beside the said river were also affected by the flood due to the absence of retaining wall which was destroyed during the previous typhoons. Close coordination with the LGU and continuous monitoring is being conducted by this office on the matter.

So far, minimal damage has been observed within Calamianes Group of Islands.

Attached are relevant photos and monitoring report of this Office.

For information and record.




RODNEY G. VERIAN



Coordination with LGUs within AOR on July 26, 2023



Photos taken during the monitoring of affected areas within the CENRO Coron AOR on July 26, 2023

✓



Photos taken during the monitoring of affected areas within the CENRO Coron AOR on July 26, 2023





Clearing and cleaning operation of areas affected in Coron, Palawan

