

REPUBLIC OF THE PHILIPPINES
PROVINCE OF PALAWAN
OFFICE OF THE BUILDING OFFICIAL

8-Beach Villa

CERTIFICATION OF FINAL INSPECTION

EL NIDO
CITY / MUNICIPALITY
AREA CODE 04115

No. 015-10-16C
Date 10-09-15

Mrs. Katleen Capulong Borja
NAME OF APPLICANT

11-12-0027

BUILDING PERMIT NO.

Brgy. Buena Suerte, El Nido, Palawan

LOCATION OF CONSTRUCTION

August 19, 2015

DATE OF COMPLETION

TYPE- III

TYPE OF CONSTRUCTION

GROUP- B

USE OR TYPE OF OCCUPANCY

10,900,516.58

COST AS-BUILT

The construction of the above-described building has been found to be in order and therefore the "Certification of Occupancy" is hereby recommended for approval.

ENGR. JUNIEB. BACOLOT
Chief, Enforcement Division/Section

CERTIFICATE OF OCCUPANCY

No. 015-10-16C
Date Issued 10-09-15

This certifies that the Mrs. Katleen Capulong Borja constructed at Brgy. Buena Suerte, El Nido, Palawan under the Building Permit No. 11-12-0027 has been inspected and found to be in conformity with the approved plans and specifications on file in this office and the provision of the "National Building Code" (P.D. 1096) and it's implementing rules and regulations and therefore the building may now be occupied.

The owner shall properly maintain this building to enhance its architectural well-being, structural stability, sanitation and fire-protective properties and shall not be used for purposes other than its intended use as stated above.

This Certification is issued in accordance with Section 309, Chapter 3 of P.D. 1096.

O.R No. 5607175-H
Amount Paid: 9,200.00
Date Paid: October 09, 2015

ENGR. RONNIE M. ALCANTARA
Building Official

Note:

A Certified Xerox copy therefore shall be posted within the premises of the building and shall not be removed without authority from the Building Official.

The official number(s) assigned to the building(s) 015-10-16C

REPUBLIC OF THE PHILIPPINES

PROVINCE OF PALAWAN

OFFICE OF THE BUILDING OFFICIAL

4-Offshore Villa

CERTIFICATION OF FINAL INSPECTION

EL NIDO

CITY / MUNICIPALITY

AREA CODE 04115

No. 015-10-19C

Date 10-09-15

Mrs. Katleen Capulong Borja

NAME OF APPLICANT

11-12-0027

BUILDING PERMIT NO.

Brgy. Buena Suerte, El Nido, Palawan

LOCATION OF CONSTRUCTION

August 19, 2015

DATE OF COMPLETION

TYPE- III

TYPE OF CONSTRUCTION

GROUP- B

USE OR TYPE OF OCCUPANCY

5,708,168.71

COST AS-BUILT

The construction of the above-described building has been found to be in order and therefore the "Certification of Occupancy" is hereby recommended for approval.

ENGR. JUNIE B. BACOLOT

Chief, Enforcement Division/Section

CERTIFICATE OF OCCUPANCY

No. 015-10-19C

Date Issued 10-09-15

This certifies that the Mrs. Katleen Capulong Borja constructed at Brgy. Buena Suerte, El Nido, Palawan under the Building Permit No. 11-12-0027 has been inspected and found to be in conformity with the approved plans and specifications on file in this office and the provision of the "National Building Code" (P.D. 1096) and it's implementing rules and regulations and therefore the building may now be occupied.

The owner shall properly maintain this building to enhance its architectural well-being, structural stability, sanitation and fire-protective properties and shall not be used for purposes other than its intended use as stated above.

This Certification is issued in accordance with Section 309, Chapter 3 of P.D. 1096.

O.R No. 5607175-H
Amount Paid: 5,000.00
Date Paid: October 09, 2015

ENGR. RONNIE M. ALCANTARA

Building Official

Note:

A Certified Xerox copy therefore shall be posted within the premises of the building and shall not be removed without authority from the Building Official.

The official number(s) assigned to the building(s) 015-10-19C

7-Owners Villa

REPUBLIC OF THE PHILIPPINES
PROVINCE OF PALAWAN
OFFICE OF THE BUILDING OFFICIAL

CERTIFICATION OF FINAL INSPECTION

EL NIDO
CITY/MUNICIPALITY
AREA CODE 04115

No. 015-10-25C
Date 10-09-15

Mrs. Katleen Capulong Borja

NAME OF APPLICANT

11-12-0027

BUILDING PERMIT NO.

Brgy. Buena Suerte, El Nido, Palawan

LOCATION OF CONSTRUCTION

August 19, 2015

DATE OF COMPLETION

TYPE-III

TYPE OF CONSTRUCTION

GROUP-B

USE OR TYPE OF OCCUPANCY

37,348,833.35

COST AS-BUILT

The construction of the above-described building has been found to be in order and therefore the "Certification of Occupancy" is hereby recommended for approval.

ENGR. JUNE B. BACOLOT

Chief, Enforcement Division/Section

CERTIFICATE OF OCCUPANCY

No. 015-10-25C
Date Issued 10-09-15

This certifies that the Mrs. Katleen Capulong Borja constructed at Brgy. Buena Suerte, El Nido, Palawan under the Building Permit No. 11-12-0027 has been inspected and found to be in conformity with the approved plans and specifications on file in this office and the provision of the "National Building Code" (P.D. 1096) and it's implementing rules and regulations and therefore the building may now be occupied.

The owner shall properly maintain this building to enhance its architectural well-being, structural stability, sanitation and fire-protective properties and shall not be used for purposes other than its intended use as stated above.

This Certification is issued in accordance with Section 309, Chapter 3 of P.D. 1096.

O.R No. 5607175-H
Amount Paid: 31,200.00
Date Paid: October 09, 2015

ENGR. RONNIE M. ACANTARA
Building Official

Note:

A Certified Xerox copy therefore shall be posted within the premises of the building and shall not be removed without authority from the Building Official.

The official number(s) assigned to the building(s) 015-10-25C

REPUBLIC OF THE PHILIPPINES
PROVINCE OF PALAWAN
OFFICE OF THE BUILDING OFFICIAL

Managers Villa

CERTIFICATION OF FINAL INSPECTION

EL NIDO
CITY/MUNICIPALITY
AREA CODE 04115

No. 015-10-24C
Date 10-09-15

Mrs. Katleen Capulong Borja

NAME OF APPLICANT

11-12-0027

BUILDING PERMIT NO.

Brgy. Buena Suerte, El Nido, Palawan

LOCATION OF CONSTRUCTION

August 19, 2015

DATE OF COMPLETION

TYPE-III

TYPE OF CONSTRUCTION

GROUP-B

USE OR TYPE OF OCCUPANCY

970,545.71.00

COST AS-BUILT

The construction of the above-described building has been found to be in order and therefore the "Certification of Occupancy" is hereby recommended for approval.

ENGR. JUNE B. BACOLOT
Chief, Enforcement Division/Section

CERTIFICATE OF OCCUPANCY

No. 015-10-24C
Date Issued 10-09-15

This certifies that the Mrs. Katleen Capulong Borja constructed at Brgy. Buena Suerte, El Nido, Palawan under the Building Permit No. 11-12-0027 has been inspected and found to be in conformity with the approved plans and specifications on file in this office and the provision of the "National Building Code" (P.D. 1096) and it's implementing rules and regulations and therefore the building may now be occupied.

The owner shall properly maintain this building to enhance its architectural well-being, structural stability, sanitation and fire-protective properties and shall not be used for purposes other than its intended use as stated above.

This Certification is issued in accordance with Section 309, Chapter 3 of P.D. 1096.

O.R No. 5607175-H
Amount Paid: 1,000.00
Date Paid: October 09, 2015

ENGR. RONNIE M. ALCANTARA
Building Official

Note:

A Certified Xerox copy therefore shall be posted within the premises of the building and shall not be removed without authority from the Building Official.

The official number(s) assigned to the building(s) 015-10-24C

REPUBLIC OF THE PHILIPPINES

PROVINCE OF PALAWAN

OFFICE OF THE BUILDING OFFICIAL

Restaurant

CERTIFICATION OF FINAL INSPECTION

EL NIDO

CITY / MUNICIPALITY

AREA CODE 04115

No. 015-10-20C

Date 10-09-15

Mrs. Katleen Capulong Borja

NAME OF APPLICANT

11-12-0027

BUILDING PERMIT NO.

Brgy. Buena Suerte, El Nido, Palawan

LOCATION OF CONSTRUCTION

August 19, 2015

DATE OF COMPLETION

TYPE- III

TYPE OF CONSTRUCTION

GROUP- B

USE OR TYPE OF OCCUPANCY

8,123,398.02

COST AS-BUILT

The construction of the above-described building has been found to be in order and therefore the "Certification of Occupancy" is hereby recommended for approval.

ENGR. JUNIE B. BACOLOT

Chief, Enforcement Division/Section

CERTIFICATE OF OCCUPANCY

No. 015-10-20C

Date Issued 10-09-15

This certifies that the Mrs. Katleen Capulong Borja constructed at Brgy. Buena Suerte, El Nido, Palawan under the Building Permit No. 11-12-0027 has been inspected and found to be in conformity with the approved plans and specifications on file in this office and the provision of the "National Building Code" (P.D. 1096) and it's implementing rules and regulations and therefore the building may now be occupied.

The owner shall properly maintain this building to enhance its architectural well-being, structural stability, sanitation and fire-protective properties and shall not be used for purposes other than its intended use as stated above.

This Certification is issued in accordance with Section 309, Chapter 3 of P.D. 1096.

O.R No. 5607175-H
Amount Paid: 6,000.00
Date Paid: October 09, 2015

ENGR. RONNIE M. ALCANTARA

Building Official

Note:

A Certified Xerox copy therefore shall be posted within the premises of the building and shall not be removed without authority from the Building Official.

The official number(s) assigned to the building(s) 015-10-20C

REPUBLIC OF THE PHILIPPINES
PROVINCE OF PALAWAN
OFFICE OF THE BUILDING OFFICIAL

Pool Bar & Pool

CERTIFICATION OF FINAL INSPECTION

EL NIDO
CITY / MUNICIPALITY
AREA CODE 04115

No. 015-10-21C
Date 10-09-15

Mrs. Katleen Capulong Borja

NAME OF APPLICANT

11-12-0027

BUILDING PERMIT NO.

Brgy. Buena Suerte, El Nido, Palawan

LOCATION OF CONSTRUCTION

August 19, 2015

DATE OF COMPLETION

TYPE- IV

TYPE OF CONSTRUCTION

GROUP- J

USE OR TYPE OF OCCUPANCY

6,679,630.91

COST AS-BUILT

The construction of the above-described building has been found to be in order and therefore the "Certification of Occupancy" is hereby recommended for approval.

ENGR. JUNIE B. BACOLOT
Chief, Enforcement Division/Section

CERTIFICATE OF OCCUPANCY

No. 015-10-21C
Date Issued 10-09-15

This certifies that the Mrs. Katleen Capulong Borja constructed at Brgy. Buena Suerte, El Nido, Palawan under the Building Permit No. 11-12-0027 has been inspected and found to be in conformity with the approved plans and specifications on file in this office and the provision of the "National Building Code" (P.D. 1096) and it's implementing rules and regulations and therefore the building may now be occupied.

The owner shall properly maintain this building to enhance its architectural well-being, structural stability, sanitation and fire-protective properties and shall not be used for purposes other than its intended use as stated above.

This Certification is issued in accordance with Section 309, Chapter 3 of P.D. 1096.

O.R No. 5607175-H
Amount Paid: 5,800.00
Date Paid: October 09, 2015

ENGR. RONNIE M. ADCANTARA
Building Official

Note:

A Certified Xerox copy therefore shall be posted within the premises of the building and shall not be removed without authority from the Building Official.

The official number(s) assigned to the building(s) 015-10-21C

Dive Shop

CERTIFICATION OF FINAL INSPECTION

No. 015-10-23C
Date 10-09-15REPUBLIC OF THE PHILIPPINES
PROVINCE OF PALAWAN
OFFICE OF THE BUILDING OFFICIALEL NIDO
CITY/MUNICIPALITY
AREA CODE 04115Mrs. Kathleen Capulong Borja

NAME OF APPLICANT

11-12-0027

BUILDING PERMIT NO.

Brgy. Buena Suerte, El Nido, Palawan

LOCATION OF CONSTRUCTION

August 19, 2015

DATE OF COMPLETION

TYPE-III

TYPE OF CONSTRUCTION

GROUP-H-2

USE OR TYPE OF OCCUPANCY

3,003,006.00

COST AS-BUILT

The construction of the above-described building has been found to be in order and therefore the "Certification of Occupancy" is hereby recommended for approval.


ENGR. JUNIE R. BACOILOT
Chief, Enforcement Division/Section

CERTIFICATE OF OCCUPANCY

This certifies that the Mrs. Kathleen Capulong Borja constructed at Brgy. Buena Suerte, El Nido, Palawan under the Building Permit No. 11-12-0027 has been inspected and found to be in conformity with the approved plans and specifications on file in this office and the provision of the "National Building Code" (P.D. 1096) and it's implementing rules and regulations and therefore the building may now be occupied.

The owner shall properly maintain this building to enhance its architectural well-being, structural stability, sanitation and fire-protective properties and shall not be used for purposes other than its intended use as stated above.

This Certification is issued in accordance with Section 309, Chapter 3 of P.D. 1096.

O.R. No. 5607175-HAmount Paid: 2,800.00Date Paid: October 09, 2015
ENGR. RONNIE M. MACANTARA
Building Official

Note:

A Certified Xerox copy therefore shall be posted within the premises of the building and shall not be removed without authority from the Building Official.

The official number(s) assigned to the building(s) 015-10-23C

6-Garden Villa

REPUBLIC OF THE PHILIPPINES
PROVINCE OF PALAWAN
OFFICE OF THE BUILDING OFFICIAL

CERTIFICATION OF FINAL INSPECTION

EL NIDO
CITY / MUNICIPALITY
AREA CODE 04115No. 015-10-17C
Date 10-09-15Mrs. Katleen Capulong BorjaNAME OF APPLICANT11-12-0027BUILDING PERMIT NO.Brgy. Buena Suerte, El Nido, PalawanLOCATION OF CONSTRUCTIONAugust 19, 2015DATE OF COMPLETIONTYPE- IIITYPE OF CONSTRUCTIONGROUP- BUSE OR TYPE OF OCCUPANCY6,704,787.71COST AS-BUILT

The construction of the above-described building has been found to be in order and therefore the "Certification of Occupancy" is hereby recommended for approval.

ENGR. JUNIE B. BACOLOT
Chief, Enforcement Division/Section

CERTIFICATE OF OCCUPANCY

No. 015-10-17C
Date Issued 10-09-15

This certifies that the Mrs. Katleen Capulong Borja constructed at Brgy. Buena Suerte, El Nido, Palawan under the Building Permit No. 11-12-0027 has been inspected and found to be in conformity with the approved plans and specifications on file in this office and the provision of the "National Building Code" (P.D. 1096) and it's implementing rules and regulations and therefore the building may now be occupied.

The owner shall properly maintain this building to enhance its architectural well-being, structural stability, sanitation and fire-protective properties and shall not be used for purposes other than its intended use as stated above.

This Certification is issued in accordance with Section 309, Chapter 3 of P.D. 1096.

O.R No. 5607175-H
Amount Paid: 5,800.00
Date Paid: October 09, 2015ENGR. RONNIE M. ADCANTARA
Building Official

Note:

A Certified Xerox copy therefore shall be posted within the premises of the building and shall not be removed without authority from the Building Official.

The official number(s) assigned to the building(s) 015-10-17C

SPA

REPUBLIC OF THE PHILIPPINES
PROVINCE OF PALAWAN
OFFICE OF THE BUILDING OFFICIAL

CERTIFICATION OF FINAL INSPECTION

EL NIDO
CITY / MUNICIPALITY
AREA CODE 04115

No. 015-10-22C
Date 10-09-15

Mrs. Katleen Capulong Borja

NAME OF APPLICANT

11-12-0027

BUILDING PERMIT NO.

Brgy. Buena Suerte, El Nido, Palawan

LOCATION OF CONSTRUCTION

August 19, 2015

DATE OF COMPLETION

TYPE- III

TYPE OF CONSTRUCTION

GROUP- H-2

USE OR TYPE OF OCCUPANCY

3,108,952.83

COST AS-BUILT

The construction of the above-described building has been found to be in order and therefore the "Certification of Occupancy" is hereby recommended for approval.

ENGR. JUNIE B. BACOLOT
Chief, Enforcement Division/Section

CERTIFICATE OF OCCUPANCY

No. 015-10-22C
Date Issued 10-09-15

This certifies that the Mrs. Katleen Capulong Borja constructed at Brgy. Buena Suerte, El Nido, Palawan under the Building Permit No. 11-12-0027 has been inspected and found to be in conformity with the approved plans and specifications on file in this office and the provision of the "National Building Code" (P.D. 1096) and it's implementing rules and regulations and therefore the building may now be occupied.

The owner shall properly maintain this building to enhance its architectural well-being, structural stability, sanitation and fire-protective properties and shall not be used for purposes other than its intended use as stated above.

This Certification is issued in accordance with Section 309, Chapter 3 of P.D. 1096.

O.R No. 5607175-H
Amount Paid: 2,800.00
Date Paid: October 09, 2015

ENGR. RONNIE M. ALCANTARA
Building Official

Note:

A Certified Xerox copy therefore shall be posted within the premises of the building and shall not be removed without authority from the Building Official.

The official number(s) assigned to the building(s) 015-10-22C

REPUBLIC OF THE PHILIPPINES

PROVINCE OF PALAWAN

OFFICE OF THE BUILDING OFFICIAL

Power House

CERTIFICATION OF FINAL INSPECTION

EL NIDO

CITY / MUNICIPALITY

AREA CODE 04115

No. 015-10-26C

Date 10-09-15

Mrs. Kathleen Capulong Borja

NAME OF APPLICANT

11-12-0027

BUILDING PERMIT NO.

Brgy. Buena Suerte, El Nido, Palawan

LOCATION OF CONSTRUCTION

August 19, 2015

DATE OF COMPLETION

TYPE- III

TYPE OF CONSTRUCTION

GROUP- B

USE OR TYPE OF OCCUPANCY

857,368.11

COST AS-BUILT

The construction of the above-described building has been found to be in order and therefore the "Certification of Occupancy" is hereby recommended for approval.

ENGR. JUNIE B. BACOLOIT

Chief, Enforcement Division/Section

CERTIFICATE OF OCCUPANCY

No. 015-10-26C

Date Issued 10-09-15

This certifies that the Mrs. Kathleen Capulong Borja constructed at Brgy. Buena Suerte, El Nido, Palawan under the Building Permit No. 11-12-0027 has been inspected and found to be in conformity with the approved plans and specifications on file in this office and the provision of the "National Building Code" (P.D. 1096) and it's implementing rules and regulations and therefore the building may now be occupied.

The owner shall properly maintain this building to enhance its architectural well-being, structural stability, sanitation and fire-protective properties and shall not be used for purposes other than its intended use as stated above.

This Certification is issued in accordance with Section 309, Chapter 3 of P.D. 1096.

O.R No. 5607175-H
Amount Paid: 1,000.00
Date Paid: October 09, 2015

ENGR. RONNIE M. ALCANTARA

Building Official

Note:

A Certified Xerox copy therefore shall be posted within the premises of the building and shall not be removed without authority from the Building Official.

The official number(s) assigned to the building(s) 015-10-26C

REPUBLIC OF THE PHILIPPINES

PROVINCE OF PALAWAN

OFFICE OF THE BUILDING OFFICIAL

Staff House-2

CERTIFICATION OF FINAL INSPECTION

EL NIDO

CITY / MUNICIPALITY

AREA CODE 04115

No. 015-10-28C

Date 10-09-15

Mrs. Katleen Capulong Borja

NAME OF APPLICANT

11-12-0027

BUILDING PERMIT NO.

Brgy. Buena Suerte, El Nido, Palawan

LOCATION OF CONSTRUCTION

August 19, 2015

DATE OF COMPLETION

TYPE- III

TYPE OF CONSTRUCTION

GROUP- B

USE OR TYPE OF OCCUPANCY

1,900,360.18

COST AS-BUILT

The construction of the above-described building has been found to be in order and therefore the "Certification of Occupancy" is hereby recommended for approval.

ENGR. JUNIE B. BACOLOT

Chief, Enforcement Division/Section

CERTIFICATE OF OCCUPANCY

No. 015-10-28C

Date Issued 10-09-15

This certifies that the Mrs. Katleen Capulong Borja constructed at Brgy. Buena Suerte, El Nido, Palawan under the Building Permit No. 11-12-0027 has been inspected and found to be in conformity with the approved plans and specifications on file in this office and the provision of the "National Building Code" (P.D. 1096) and it's implementing rules and regulations and therefore the building may now be occupied.

The owner shall properly maintain this building to enhance its architectural well-being, structural stability, sanitation and fire-protective properties and shall not be used for purposes other than its intended use as stated above.

This Certification is issued in accordance with Section 309, Chapter 3 of P.D. 1096.

O.R No. 5607175-H
Amount Paid: 1,800.00
Date Paid: October 09, 2015

ENGR. RONNIE M. ALCANTARA

Building Official

Note:

A Certified Xerox copy therefore shall be posted within the premises of the building and shall not be removed without authority from the Building Official.

The official number(s) assigned to the building(s) 015-10-28C

REPUBLIC OF THE PHILIPPINES

PROVINCE OF PALAWAN

OFFICE OF THE BUILDING OFFICIAL

Staff House-1

CERTIFICATION OF FINAL INSPECTION

EL NIDO
CITY / MUNICIPALITY
AREA CODE 04115

No. 015-10-27C
Date 10-09-15

Mrs. Katleen Capulong Borja

NAME OF APPLICANT

11-12-0027

BUILDING PERMIT NO.

Brgy. Buena Suerte, El Nido, Palawan

LOCATION OF CONSTRUCTION

August 19, 2015

DATE OF COMPLETION

TYPE- III

TYPE OF CONSTRUCTION

GROUP- B

USE OR TYPE OF OCCUPANCY

5,928,855.49

COST AS-BUILT

The construction of the above-described building has been found to be in order and therefore the "Certification of Occupancy" is hereby recommended for approval.

ENGR. JUNE R. BACOLOT

Chief, Enforcement Division/Section

CERTIFICATE OF OCCUPANCY

No. 015-10-27C
Date Issued 10-09-15

This certifies that the Mrs. Katleen Capulong Borja constructed at Brgy. Buena Suerte, El Nido, Palawan under the Building Permit No. 11-12-0027 has been inspected and found to be in conformity with the approved plans and specifications on file in this office and the provision of the "National Building Code" (P.D. 1096) and it's implementing rules and regulations and therefore the building may now be occupied.

The owner shall properly maintain this building to enhance its architectural well-being, structural stability, sanitation and fire-protective properties and shall not be used for purposes other than its intended use as stated above.

This Certification is issued in accordance with Section 309, Chapter 3 of P.D. 1096.

O.R No. 5607175-H
Amount Paid: 5,000.00
Date Paid: October 09, 2015

ENGR. RONNIE M. ALCANTARA
Building Official

Note:

A Certified Xerox copy therefore shall be posted within the premises of the building and shall not be removed without authority from the Building Official.

The official number(s) assigned to the building(s) 015-10-27C

Common Toilet

REPUBLIC OF THE PHILIPPINES
PROVINCE OF PALAWAN
OFFICE OF THE BUILDING OFFICIAL

CERTIFICATION OF FINAL INSPECTION

EL NIDO

CITY / MUNICIPALITY
AREA CODE 04115No. 015-10-29C
Date 10-09-15Mrs. Katleen Capulong Borja
NAME OF APPLICANT

11-12-0027

BUILDING PERMIT NO.

Brgy. Buena Suerte, El Nido, Palawan

LOCATION OF CONSTRUCTION

August 19, 2015

DATE OF COMPLETION

TYPE- III

TYPE OF CONSTRUCTION

GROUP- J

USE OR TYPE OF OCCUPANCY

512,368.10

COST AS-BUILT

The construction of the above-described building has been found to be in order and therefore the "Certification of Occupancy" is hereby recommended for approval.

ENGR. JUNE B. BACOLOT
Chief, Enforcement Division/Section

CERTIFICATE OF OCCUPANCY

No. 015-10-29C
Date Issued 10-09-15

This certifies that the Mrs. Katleen Capulong Borja constructed at Brgy. Buena Suerte, El Nido, Palawan under the Building Permit No. 11-12-0027 has been inspected and found to be in conformity with the approved plans and specifications on file in this office and the provision of the "National Building Code" (P.D. 1096) and it's implementing rules and regulations and therefore the building may now be occupied.

The owner shall properly maintain this building to enhance its architectural well-being, structural stability, sanitation and fire-protective properties and shall not be used for purposes other than its intended use as stated above.

This Certification is issued in accordance with Section 309, Chapter 3 of P.D. 1096.

O.R No. 5607175-H
Amount Paid: 800.00
Date Paid: October 09, 2015ENGR. RONNIE M. ALCANTARA
Building Official

Note:

A Certified Xerox copy therefore shall be posted within the premises of the building and shall not be removed without authority from the Building Official.

The official number(s) assigned to the building(s) 015-10-29C

REPUBLIC OF THE PHILIPPINES
PROVINCE OF PALAWAN
OFFICE OF THE BUILDING OFFICIAL

5-Lake Villa

CERTIFICATION OF FINAL INSPECTION

EL NIDO
CITY / MUNICIPALITY
AREA CODE 04115

No. 015-10-18C
Date 10-09-15

Mrs. Katleen Capulong Borja

NAME OF APPLICANT

11-12-0027

BUILDING PERMIT NO.

Brgy. Buena Suerte, El Nido, Palawan

LOCATION OF CONSTRUCTION

August 19, 2015

DATE OF COMPLETION

TYPE- III

TYPE OF CONSTRUCTION

GROUP- B

USE OR TYPE OF OCCUPANCY

7,202,323.05

COST AS-BUILT

The construction of the above-described building has been found to be in order and therefore the "Certification of Occupancy" is hereby recommended for approval.

ENGR. JUNIE B. BACOLOT
Chief, Enforcement Division/Section

CERTIFICATE OF OCCUPANCY

No. 015-10-18C
Date Issued 10-09-15

This certifies that the Mrs. Katleen Capulong Borja constructed at Brgy. Buena Suerte, El Nido, Palawan under the Building Permit No. 11-12-0027 has been inspected and found to be in conformity with the approved plans and specifications on file in this office and the provision of the "National Building Code" (P.D. 1096) and it's implementing rules and regulations and therefore the building may now be occupied.

The owner shall properly maintain this building to enhance its architectural well-being, structural stability, sanitation and fire-protective properties and shall not be used for purposes other than its intended use as stated above.

This Certification is issued in accordance with Section 309, Chapter 3 of P.D. 1096.

O.R No. 5607175-H
Amount Paid: 6,200.00
Date Paid: October 09, 2015

ENGR. RONNIE M. ALCANTARA
Building Official

Note:

A Certified Xerox copy therefore shall be posted within the premises of the building and shall not be removed without authority from the Building Official.

The official number(s) assigned to the building(s) 015-10-18C