



March 11, 2023

MEMORANDUM

FOR : The OIC, PENR Officer

THRU : The Chief, TSD/ SvEMS

FROM : The Undersigned

SUBJECT : **JOINT INCIDENT REPORT ON TILTED MV CATRIONA IN THE VICINITY WATERS OFF NAVOTAS, CALAPAN CITY, ORIENTAL MINDORO AS OF 3:00 PM OF MARCH 11, 2023**

Submitted is the Joint Incident Report regarding the tilted MV Catriona in the vicinity waters off Navotas, Calapan City, Oriental Mindoro as of 3:00 pm of March 11, 2023. The maritime incident happened today around 2:55 am. The information was obtained in coordination with the Philippine Coast Guard (PCG) - Coast Guard Station Oriental Mindoro.

Based on the inspection and monitoring conducted by the undersigned, the MV Catriona emanated from Japan en route to Davao. The vessel has five (5) male Japanese crew members with age group 74-86 years old.


Accordingly, as per the information, the MV Catriona while underway encountered an inclement weather condition and accidentally incurred damage. Thus, causing the motor vessel to tilt (vessel listing).


The Coast Guard Station Oriental Mindoro conducted Search and Rescue (SAR) operation and successfully salvaged all the crew members. Further, a medical check-up was done to them to ensure their good health condition.

The distressed vessel has been towed to the Philippine Ports Authority (PPA) around 5:00 am for proper management. The PCG deployed its personnel to ascertain the cause of maritime incident.

To date, the PCG is draining the uncontaminated water out of the motor vessel. Meanwhile, there is no oil spill report as of this moment. The undersigned shall continuously coordinate with the PCG, PPA and the Local Government Unit of Calapan City to monitor and provide update on the maritime accident.

For information and further instruction.


MACKALEY P. MARTINEZ
Forester I/ Information Officer/
Planning Officer – CENRO Socorro


GERRY C. MAMIGO
CDO II – PENRO Oriental Mindoro


NELSON S. FLORIDA
Forest Ranger – PENRO Oriental Mindoro


RICK U. DUMADAG
Senior FMS – PENRO Oriental Mindoro



Figure 1. Coordination with the PPA and PCG regarding the MV Catriona maritime incident.



Figure 2. Pumping of uncontaminated water out of the vessel.



Figure 3. PCG inspecting the damage of MV Catriona.



Figure 4. Inspection and monitoring of MV Catriona maritime incident.