




Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
PROVINCIAL ENVIRONMENT AND NATURAL RESOURCES OFFICE
Bgy. Sta. Monica, Puerto Princesa City, Palawan
Telfax No. (048) 434 - 8791
Email Add: penropalawan@denr.gov.ph



December 2, 2022

MEMORANDUM

FOR : The Regional Executive Director
DENR MIMAROPA Region
1515 DENR By the Bay Building, Roxas Boulevard,
Barangay 668, Ermita, Manila

THRU : The OIC, ARD for Technical Services

FROM : Provincial Environment and
Natural Resources Officer

SUBJECT : **CONSOLIDATED REPORT ON THE SILTATION ALONG
MAREMEGMEG BEACH CAUSED BY ON-GOING
BENCHING OF BAYVIEW HOTEL AT BARANGAY
CORONG-CORONG, EL NIDO, PALAWAN**

Forwarded is the Memorandum dated 16 November 2022 of CENRO Taytay transmitting the attached memorandum dated 24 October 2022 of Assistant Protected Area Superintendent (APASu)

It is informed that the PAMO ENTMRPA is advised to conduct the enumerated actions suggested on the said report.

For information, record and further instruction.

DENR-PALAWAN
PENRO-RECORDS
RELEASED
By chea CN 2022-3262
Date 05 DEC 2022


FELIZARDO B. CAYATOC

Copy Furnished:
RGT/EMU Doc. No. 10666



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region

COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE

By the National Highway, Poblacion, Taytay, Palawan 5312

Mobile: 0926-505-9335, TM-0912-171-3889 TNT

Email: cenro.taytay@denr.gov.ph

Regional Office

RECEIVED

November 16, 2022

MEMORANDUM

BY:

DATE: 11-20-2022 22-10666

FOR : The Provincial Environment and Natural Resources Officer- Palawan
Sta. Monica, Puerto Princesa City

FROM : The Community Environment and Natural Resources Officer
This jurisdiction

SUBJECT : **CONSOLIDATED REPORT ON THE SILTATION ALONG
MAREMEGMEG BEACH CAUSED BY ON-GOING BENCHING
OF BAYVIEW HOTEL AT BARANGAY CORONG-CORONG, EL
NIDO, PALAWAN**

Respectfully forwarded is the memorandum dated October 24, 2022 of Assistant Protected Area Superintendent (APASu) Jenuel P. Casel pertaining to the above subject.

Please be informed that on September 17, 2022, the PAMO personnel conducted an inspection and monitoring on the damaged caused by Typhoon Josie in compliance to the instruction of PASU of ENTMRPA. The National Road in front of the Bayview Hotel was monitored to be covered with mud caused by the benching activity of the said establishment.

Further, on September 28-29, the OIC-EMS Chief Dennis Aldrin Velasco R.P.F. conducted inspection and monitoring to address the various Facebook issue on siltation along Maremegmeg Beach. During the said reinspection, the proponent was able to immediately clear the road of debris and mud. The siltation along Maremegmeg beach is brought about by the excavation activities along the ridge of Sitio Maremegmeg one of which is the benching activity of the Bayview Hotel.

In view of the above, the PAMO ENTMRPA is hereby advised to conduct the following:

1. Conduct continuous monitoring in the area;
2. Coordinate with the concerned agencies involved during the 2nd virtual conference dated February 17, 2022 to follow up their commitment during the said meeting; and
3. Ensure the compliance of the Bayview Hotel on the recommendations during the 2nd virtual conference and submit periodic update on the matter.

For information, record and further instruction.

CONRADO M. CORPUZ

R

**DENR CENRO
TAYTAY, PALAWAN
RELEASED**

BY:

DATE:

NOV 16 2022

3347



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE
By the National Highway, Poblacion, Taytay, Palawan 5312
Mobile: 0926-505-9335 TM 0912-171-3889 TNT
Email: cenrotaytay@denr.gov.ph

November 16 , 2022

MEMORANDUM

TO : **The Protected Area Superintendent**
El Nido-Taytay Managed Resource Protected Area
El Nido, Palawan

FROM : The Community Environment and Natural Resources Officer
This jurisdiction

SUBJECT : **CONSOLIDATED REPORT ON THE SILTATION ALONG
MAREMEGMEG BEACH CAUSED BY ON-GOING BENCHING
OF BAYVIEW HOTEL AT BARANGAY CORONG-CORONG, EL
NIDO, PALAWAN**

This is to acknowledge the receipt of your memorandum dated October 24, 2022 relative to the various Facebook post pertaining to the above subject.

In this regard, you are hereby advised to conduct continuous monitoring in the area, coordinate with the concerned agencies involved during the 2nd virtual conference dated February 17, 2022 to follow up their commitment during the said meeting and ensure the compliance of the Bayview Hotel during virtual conference and submit periodic update on the matter.

For guidance and compliance.

CONRADO M. CORPUZ

R

Copy furnished:

Regional Executive Director, DENR-MIMAROPA
Provincial Environment and Natural Resources Officer – Palawan

**DENR CENRO
TAYTAY, PALAWAN
RELEASED**

BY: 96
DATE: NOV 16 2022 CN 3348



October 24, 2022

MEMORANDUM

FOR : The Community Environment and Natural Resources Officer
Taytay, Palawan

FROM : The Protected Area Superintendent
El Nido - Taytay Managed Resource Protected Area

SUBJECT : **CONSOLIDATED REPORT ON THE SILTATION ALONG MAREMEGMEG BEACH CAUSED BY ON-GOING BENCHING OF BAYVIEW HOTEL AT BARANGAY CORONG-CORONG, EL NIDO, PALAWAN**

**DENR CENRO
TAYTAY, PALAWAN
RECEIVED**
BY: *Jub*
DATE: 10-27-22 CN 6204

Respectfully forwarded is the two (2) consolidated report from Forest Ranger Herson Y. Caliao and The Chief, EMS Dennis Aldrin O. Velasco R.P.F dated September 22, 2022 and September 29, 2022 relative to the various Facebook post pertaining to the above subject.

Please be informed, that on September 17, 2022 this office conducted ocular inspection and monitoring along the South national highway of the municipality of El Nido to check the areas were flooding and possible landslide. Based on the report, the team noticed that the national road in front of Bayview Hotel was covered by mud caused by benching activity of the said establishment. On September 28-29, 2022 this office re-inspection the area, based on the ocular inspection the proponent was able to immediately clean the road of debris and mud for motorist to pass safely.

Based on the above findings, this office recommends the following:

1. Conduct continuous monitoring in the area;
2. Conduct follow-up pertaining to the commitments of concerned agencies as a result of 2nd virtual conference dated February 17, 2022;
3. Conduct a follow-up and require the proponent to submit their compliance on the recommendations during 2nd virtual conference dated February 17, 2022;

For information, record and further instruction.

“For the Protected Area Superintendent:

**DENR - PAO
ENTMRPA,
El Nido, Palawan**
RELEASED
By: *Caratiana*
Date: 10-24-22
C.N.: 1042

Jub
JENUEL P. CASEL
PMF/ Assistant PASu
In-Charge, ENTMRPA-PAMO *el*




MEMORANDUM

FOR : The Protected Area Superintendent
El Nido-Taytay Managed Resource Protected Area

FROM : Forest Ranger

SUBJECT : REPORT ON SILTATION ALONG MAREMEGMEG BEACH
CAUSED BY ON-GOING BENCHING OF BAYVIEW HOTEL AT
BARANGAY CORONG-CORONG, EL NIDO, PALAWAN

September 22, 2022



This pertains to instruction of PASu Mildred A. Suza to conduct monitoring along Sitio Lugadia, Barangay Corong-corong, El Nido, Palawan regarding the possible flooding and siltation caused by heavy rains brought by Typhoon Nanmadol (Typhoon Josie) that entered the Philippine Area of Responsibility (PAR) on September 16, 2022.

Please be informed that the undersigned along with Forest Protection Officer Nolan Llanera conducted ocular inspection dated September 17, 2022 along the South National Highway of the municipality and checked areas where flooding and possible landslides might have occurred.

During the ocular inspection, the undersigned noticed that the national road in front of Bayview Hotel was covered by mud caused by benching activity of the said establishment. Based on initial inspection, this event also causes siltation and discoloration along Maremegmeg Beach as the run-off flows to the nearby beach.

With this, the undersigned recommends as follows:

1. Conduct continuous monitoring in the area;
2. Conduct follow up pertaining to the commitments of concerned agencies as a result of 2nd virtual conference dated February 17, 2022;
3. Conduct a follow up and require the proponent to submit their compliance on the recommendations during 2nd virtual conference dated February 17, 2022;

Attached herewith were the geotagged photos during the activity.

For information, record and further instruction.




HERSON Y. CALIAO
Forest Ranger

PHOTO DOCUMENTATION



CERTIFICATION

This is to certify that the above photos were true and correct and taken at the vicinity of Bayview Hotel and Maremegmeg Beach on September 17, 2022






HERSON Y. CALIAO
Forest Ranger

PHOTO DOCUMENTATION



CERTIFICATION

This is to certify that the above photos were true and correct and taken at the vicinity of Bayview Hotel and Maremegmeg Beach on September 17, 2022


HERSON Y. CALIAO
Forest Ranger



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region

COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE

By the National Highway, Poblacion, Taytay, Palawan 5312

Mobile: 0926-505-9335 TM 0912-171-3889 TNT

Email: cenrotaytay@denr.gov.ph

September 29, 2022

MEMORANDUM

FOR : The Community Environment and Natural Resources Officer
THRU : The Protected Area Superintended ENTMRPA
FROM : The Chief, Enforcement and Monitoring Section
SUBJECT : **REPORT ON THE ALLEGED SILTATION BROUGHT ABOUT BY SOIL EROSION FROM THE LANDSLIDE PRONE AREA BESIDE THE BENCHING AREA OF BAY VIEW RESORT ALONG LAS CABAÑAS BEACH, CORONG-CORONG EL NIDO, PALAWAN**



This pertains to the various Facebook post relative to the above subject. (please see attached Facebook posts).


Please be informed that the undersigned conducted inspection on the area identified in the Facebook post. The alleged siltation came from the soil eroded from the benching project of Mr. Edgardo Trinidad, after the heavy rains brought about by heavy rains last September 16-17, 25-26, 2022.

The Office already conducted several technical conferences to regarding this matter wherein some actions were recommended by the MGB and EMB to address this issue.

It can not be helped that surface run-off would occur during strong rains and for the road to get muddy during incidents of light to medium rain. Based on the ocular inspection conducted, last September 28-29, 2022 the proponent was able to immediately clean the road of debris and mud for motorist to pass safely. The surface run-off which drained to the adjacent coastal area was already dissolved.


The undersigned recommends a follow-up and submit the status on the actions recommended by the EMB and MGB relative to this matter. Furthermore, it is also recommended that Mr. Edgardo Trinidad be required to use additional porous or polymeric fiber on his benching project to avoid or minimize soil erosion in the area.

For your information, consideration, further instructions


DENNIS ALDRIN O. VELASCO R.P.F



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE
By the National Highway, Poblacion, Taytay, Palawan 5312
Mobile: 0926-505-9335 TM 0912-171-3889 TNT
Email: cenrotaytay@denr.gov.ph



Photos of the reported Facebook posts and comments



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE
By the National Highway, Poblacion, Taytay, Palawan 5312
Mobile: 0926-505-9335 TM 0912-171-3889 TNT
Email: cenrotaytay@denr.gov.ph



Geotagged photos showing the road affected by the surface run-off from the benching project



Geotagged photos showing the road affected by the surface run-off from the benching project




Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region

COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE

By the National Highway, Poblacion, Taytay, Palawan 5312

Mobile: 0926-505-9335 TM 0912-171-3889 TNT

Email: cenrotaytay@denr.gov.ph



Geotagged photos showing the area affected by siltation from the surface run-off