




Republic of the Philippines
Department of Environment and Natural Resources
Provincial Environment and Natural Resources Office
MIMAROPA Region

Bgy. Sta. Monica, Puerto Princesa City, Palawan

E-mail: penropalawan@denr.gov.ph

Telfax No. (048) 433-5638 / (048) 433-5638



November 16, 2022

MEMORANDUM

FOR : The Regional Executive Director
DENR MIMAROPA
1515 DENR By the Bay Bldg., Roxas Boulevard,
Barangay 668, Ermita Manila

THRU : The OIC, Assistant Regional Director for Technical Services

FROM : The Provincial Environment and
Natural Resources Officer


SUBJECT : **REPORT ON THE REPAIR AND MAINTENANCE OF
FACILITIES OF EL NIDO-TAYTAY MANAGED RESOURCE
PROTECTED AREA (ENTMRPA) FOR OCTOBER 2022**

Forwarded is the memorandum dated October 28, 2022 from CENRO Taytay along with the Report on the Repair and Maintenance of facilities of El Nido-Taytay Managed Resource Protected Area (ENTMRPA) for October 2022.


Please be informed that the Protected Area Management Office (PAMO) of ENTMRPA conducted activities related to the maintenance of facilities of the protected area (PAMO, Dive House, Forest Product Monitoring Station II and IV).

For information and record.

“For and in the absence of the PENRO”


RONIE B. GANDEZA
DMO IV/ OIC TSD
Officer-In-Charge



DENR-PALAWAN
PENRO-RECORDS
RELEASED
By 
Date: 18 NOV 2022 22-3108



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region

COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE

By the National Highway, Poblacion, Taytay, Palawan 5312

Mobile: 0926-505-9335 TM 0912-171-3889 TNT

Email: cenrotaytay@denr.gov.ph

October 28, 2022

MEMORANDUM

FOR : The Provincial Environment and Natural Resources Officer- Palawan
Sta. Monica, Puerto Princesa City

FROM : The Community Environment and Natural Resources Officer
This jurisdiction

SUBJECT : **REPORT ON THE REPAIR AND MAINTENANCE OF
FACILITIES OF EL NIDO-TAYTAY MANAGED RESOURCE
PROTECTED AREA (ENTMRPA) FOR OCTOBER 2022**

Respectfully forwarded is the memorandum dated October 24, 2022 from Assistant Protected Area Superintendent (APASu) Jenuel P. Casel pertaining to the target activity on Maintenance of Facilities, item 5 Ecotourism Program and Impact under Protected Area Management and Development Sub-program for El Nido-Taytay Managed Resource Protected Area (ENTMRPA), El Nido, Palawan. This serves as **Means of Verification (MoV)** on the activity for the month of October 2022.

The PAMO-ENTMRPA is hereby reminded that the subject of the maintenance of facilities are the established DENR facilities found within the protected area and should not include the on-going construction of the lumber shed.

For information and record.

ALAN VALLE
R

Cc: PAMO-ENTMRPA

DENR CENRO
TAYTAY, PALAWAN
RELEASED
BY: 16
DATE: NOV 04 2022 CN 3198



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
Community Environment and Natural Resources Office
EL NIDO-TAYTAY MANAGED RESOURCE PROTECTED AREA
Calle Real, Bgy. Masagana, El Nido, Palawan 5313
Telephone No. 048-716-0674
Email: entmrpa@gmail.com


October 24, 2022

MEMORANDUM

FOR : The Community Environment and Natural Resources Officer
Taytay, Palawan

FROM : The Protected Area Superintendent
El Nido - Taytay Managed Resource Protected Area

SUBJECT : **REPORT ON THE REPAIR AND MAINTENANCE OF FACILITIES OF EL NIDO-TAYTAY MANAGED RESOURCE PROTECTED AREA (ENTMRPA) FOR OCTOBER 2022**




Respectfully forwarded is the memorandum dated October 20, 2022 from Park Ranger Manuelito F. Jongay pertaining to the target activity under Eco-Tourism Program facilities and maintenance within El Nido-Taytay Managed Resource Protected Area (ENTMRPA).

Please be informed that the ENTMRPA-PAMO conducted repair and maintenance of facilities such as usual cleaning of surroundings, repair of roof, gate and dirty kitchen; on-going construction of lumber shed area and doing minor repairs in the facilities.

This serves as Means of Verification (MOV) for the Month of October 2022.

For information and record.

“For the Protected Area Superintendent:



JENUEL P. CASEL
PMF/ Assistant PASu
In-Charge, ENTMRPA-PAMO *22*



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
Community Environment and Natural Resources
EL NIDO-TAYTAY MANAGED RESOURCE PROTECTED AREA
Calle Real, Barangay Masagana, El Nido, Palawan, 5313
Contact No. GLOBE (0917-1103-262)
Email: denrpao_elnidopal@yahoo.com / entmrpa@gmail.com


October 20, 2022

MEMORANDUM

FOR : The Protected Area Superintendent
El Nido-Taytay Managed Resource Protected Area
El Nido, Palawan

FROM : ENTMRPA Staff
El Nido-Taytay Managed Recourse Protected Area

SUBJECT : **PROGRESS REPORT ON THE MAINTENANCE OF FACILITIES WITHIN EL NIDO-TAYTAY MANAGED RESOURCE PROTECTED AREA (ENTMRPA), EL NIDO, PALAWAN FOR OCTOBER 2022**



This pertains to the target activity under Eco-Tourism Program facilities and maintenance within El Nido-Taytay Managed Resource Protected Area (ENTMRPA), El Nido, Palawan.

Please be informed that for the month of October 2022 up to date, this office was able to perform the following activities listed below as part of the maintenance of facilities in El Nido, Palawan.

Unit	Facility	Location	Activity
1.	Protected Area Management Office (PAMO)	Bgy. Masagana, El Nido, Palawan	<ul style="list-style-type: none">• Usual clean-up of the Office• Usual clean-up of Guest room• Changed light bulbs• Washed and clean laundry (bedsheets, pillowcase and blanket)
2.	Dive House	Bgy. Corong-Corong, El Nido, Palawan	<ul style="list-style-type: none">• Usual clean-up of the dive house and the yard• Repair of gate (entrance and exit)
3.	Forest Product Monitoring Station (FPMS)- II	Bgy. Bagong Bayan, El Nido, Palawan	<ul style="list-style-type: none">• Usual clean-up of the house and the yard• Repair of dirty kitchen
4.	Forest Product Monitoring Station (FPMS)- IV	Lamoro, Bgy. Pasadena, El Nido, Palawan	<ul style="list-style-type: none">• On-going construction of lumber shed area• Repair roof of station

Attached herewith are the geotagged photos for references.

For information and record.


MANUELITO JONGAY
Park Ranger



October 20, 2022

MEMORANDUM

FOR : The Protected Area Superintendent
El Nido-Taytay Managed Resource Protected Area
El Nido, Palawan

FROM : ENTMRPA Staff
El Nido-Taytay Managed Resource Protected Area

SUBJECT : **PROGRESS REPORT ON THE MAINTENANCE OF FACILITIES WITHIN EL NIDO-TAYTAY MANAGED RESOURCE PROTECTED AREA (ENTMRPA), EL NIDO, PALAWAN FOR OCTOBER 2022**



This pertains to the target activity under Eco-Tourism Program facilities and maintenance within El Nido-Taytay Managed Resource Protected Area (ENTMRPA), El Nido, Palawan.

Please be informed that for the month of October 2022 up to date, this office was able to perform the following activities listed below as part of the maintenance of facilities in El Nido, Palawan.

Unit	Facility	Location	Activity
1.	Protected Area Management Office (PAMO)	Bgy. Masagana, El Nido, Palawan	<ul style="list-style-type: none">• Usual clean-up of the Office• Usual clean-up of Guest room• Changed light bulbs• Washed and clean laundry (bedsheets, pillowcase and blanket)
2.	Dive House	Bgy. Corong-Corong, El Nido, Palawan	<ul style="list-style-type: none">• Usual clean-up of the dive house and the yard• Repair of gate (entrance and exit)
3.	Forest Product Monitoring Station (FPMS)- II	Bgy. Bagong Bayan, El Nido, Palawan	<ul style="list-style-type: none">• Usual clean-up of the house and the yard• Repair of dirty kitchen
4.	Forest Product Monitoring Station (FPMS)- IV	Lamoro, Bgy. Pasadena, El Nido, Palawan	<ul style="list-style-type: none">• On-going construction of lumber shed area• Repair roof of station

Attached herewith are the geotagged photos for references.


For information and record.


MANUELITO JONGAY
Park Ranger

PHOTO DOCUMENTATION



FPMS-II BAGONG BAYAN STATION



PROTECTED AREA MANAGEMENT OFFICE (PAMO)

CERTIFICATION

I hereby certify that the above photos are true and correct and taken during the conducted repair and maintenance of facilities for October 2022.



MANUELITO JONGAY
Park Ranger

PHOTO DOCUMENTATION



BEFORE



AFTER

CERTIFICATION

This is to certify that the above photos were true and correct and taken by the undersigned during the ENTMRPA personnels conducted cleaning-up the sorroundings of Divehouse station at Barangay Corong-Corong, El Nido Palawan on October 10, 2022.

zi
MANUELITO F. JONGAY
Park Ranger

PHOTO DOCUMENTATION



BEFORE



AFTER

CERTIFICATION

This is to certify that the above photos were true and correct and taken by the undersigned during the ENTMRPA personnels conducted maintenance and protection of facilities for repair the gate entrance and exit of Diver House Station in Barangay Corong-Corong, El Nido Palawan on October 11, 2022.

Zi
MANUELITO F. JONGAY
Park Ranger

PHOTO DOCUMENTATION



BEFORE




AFTER

CERTIFICATION

This is to certify that the above photos were true and correct and taken by the undersigned during the ENTMRPA personnel repairing the roof of FPMS-IV located at Sitio Lamoro, Barangay Pasadeña, El Nido Palawan on October 15, 2022.


MANUELITO F. JONGAY
Park Ranger

PHOTO DOCUMENTATION



BEFORE



AFTER

CERTIFICATION

This is to certify that the above photos were true and correct and taken by the undersigned during the ENTMRPA personnel constructed the Lumber Shed located at Sitio Lamoro, Barangay Pasadeña, El Nido Palawan on October 2022.


MANUELITO F. JONGAY
Park Ranger