



Republic of the Philippines  
Department of Environment and Natural Resources  
**MIMAROPA Region**  
**Provincial Environment and Natural Resources Office**  
Bgy. Sta. Monica, Puerto Princesa City, Palawan  
E-mail: penropalawan@denr.gov.ph  
Telfax No. (048) 433-5638



October 28, 2022

**MEMORANDUM**

**FOR : The Regional Executive Director**  
1515 DENR By the Bay Building,  
Roxas Boulevard, Barangay 668  
Ermita, Manila

**THRU : The OIC- Assistant Regional Director for Technical Services**  
MIMAROPA Region

**FROM : The Provincial Environment and**  
Natural Resources Officer

**SUBJECT : SITE MONITORING / INSPECTION REPORT**  
**ON THE CONSTRUCTION OF SWIS PROJECT**  
**LOCATED IN BGY. DUMANGUENA, NARRA,**  
**PALAWAN**


Forwarded is the monitoring /inspection report of the Project Monitoring and Evaluation Officer of PENRO-Conservation and Development Section, dated October 24, 2022 regarding the Construction of Small Water Impounding System located in barangay Dumanguena, Narra, Palawan.


Based on the report, the construction was estimated to 82.99% completed and an ongoing works include installation of pipes, structural concrete, reinforcing steel bars grade 40 and forms and falseworks. These remaining works are estimated to complete before the end of November.

Please find attached photo documentation taken during the inspection.

For his information and record.

For the PENRO:

  
**FRANKLIN G. HERNANDEZ**  
Chief Management Services Division  
Officer In Charge





Republic of the Philippines  
Department of Environment and Natural Resources  
**MIMAROPA Region**  
**Provincial Environment and Natural Resources Office**  
Bgy. Sta. Monica, Puerto Princesa City, Palawan  
E-mail: penropalawan@denr.gov.ph  
Telfax No. (048) 433-5638

October 26, 2022

**MEMORANDUM**

**FOR :** The Provincial Environment and  
Natural Resources Officer  
Sta. Monica, Puerto Princesa City

**THRU :** The Chief, PENRO CDS

**FROM :** The Project Monitoring and Evaluation Officer  
CDS Technical Staff


**SUBJECT :** **SITE INSPECTION REPORT ON THE  
CONSTRUCTION OF SWIS PROJECT  
LOCATED IN BGY. DUMANGUENA,  
NARRA, PALAWAN**

Submitted is the report of the undersigned on the conducted monitoring of the construction of Small Water Impounding System (SWIS) project located in barangay Dumanguena, Narra, Palawan last October 19, 2022.

Based on the actual inspection conducted we conclude 566/\*6 that the contractor had accomplished 82.99% and have an on-going works that includes installation of pipes, structural concrete Class A, reinforcing steel bars grade 40 and forms and falseworks.

Please find attached photo documentation taken during the time of monitoring in the project site together with the representatives from CENRO Quezon and be form part of our Means of Verification (MOV) for target activity for cy 2022.


For his information and record.

  
**RAYMART B. FUENTES**




GEO-TAGGED PHOTOS TAKEN ON OCTOBER 19, 2022

CONCRETE FILTRATION BOX










CONCRETE RESERVOIR





CONCRETE IMPOUNDING







9°24'58"N, 118°24'19"E

accuracy: 5m

10/19/22  
2:17 PM