



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
PROVINCIAL ENVIRONMENT AND NATURAL RESOURCES OFFICE

NOV 02 2022

DENR MIMAROPA RECORDS SECTION
RECEIVED
07 NOV 2022
☐ INCOMING ☐ OUTGOING
DATE NO.

MEMORANDUM

FOR : The Regional Executive Director
DENR MIMAROPA Region
1515 DENR By the Bay Building, Roxas Boulevard,
Barangay 668, Ermita, Manila

THRU : The ARD for Technical Services

FROM : The OIC, PENR Officer

SUBJECT : **REPORT ON MONITORING OF FACILITIES WITHIN MT. CALAVITE WILDLIFE SANCTUARY (MCWS) FOR FOURTH QUARTER CY 2022**

Forwarded is the memorandum dated October 24, 2022 of CENRO Sablayan regarding monitoring of facilities within Mount Calavite Wildlife Sanctuary (MCWS) for the Fourth Quarter of CY 2022.

Attached herewith are the geotagged pictures of Ranger Station and three (3) monitoring stations located at Sitios Pinagbayanan and Hinugasan located in Brgy. Harrison, Paluan, Occidental Mindoro.

For information and record.

ERNESTO E. TAÑADA



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE

October 24, 2022

MEMORANDUM

FOR : The Regional Executive Director
DENR MIMAROPA Region
1515 L&S Bldg. Roxas Boulevard
Ermita, Manila

RECORDED

Date: 10-24-22
By: 98

THRU : The OIC, PENR Officer

FROM : The CENR Officer



SUBJECT : REPORT ON MONITORING OF FACILITIES WITHIN MT.
CALAVITE WILDLIFE SANCTUARY (MCWS) FOR FOURTH
QUARTER CY 2022

Respectfully submitted herewith is the report of Mt. Calavite Wildlife Sanctuary Protected Area Management Office on the monitoring of facilities within MCWS for fourth quarter CY 2022.

Attached are the photos of the monitored and maintained facilities.

For your information and record.


FOR. ANASTACIO A. SANTOS, MPA





Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE

October 24, 2022

MEMORANDUM

FOR : The CENR Officer

FROM : The Protected Area Superintendent
Mt. Calavite Wildlife Sanctuary

SUBJECT : REPORT ON MONITORING OF FACILITIES WITHIN MT.
CALAVITE WILDLIFE SANCTUARY FOR FOURTH
QUARTER CY 2022

Please be informed that the Mt. Calavite Wildlife Sanctuary-Protected Area Management Office conducted monitoring of facilities within MCWS for the 4th quarter of CY 2022. The following facilities are as follows:

FACILITIES	REMARKS
1. Ranger Station (1)	Aside from its function as Ranger Station, the facility is being used as temporary office of MCWS-PAMO Staff, venue during the conduct of meetings and other activities. The color of its exterior will be re-painted in CY 2023 in accordance with DAO 2009-09
2. Monitoring Stations (3)	Monitoring stations located at Sitios Pinagbayanan and Hinugasan, all located in Brgy. Harrison, Paluan, Occidental Mindoro are well maintained and can be used by the PA Rangers as their temporary shelter during patrol works. However, portion of the roofing of monitoring station located at Calangigan is already worn out, hence, will be replaced next year (2023).

Attached are the photos of the monitored and maintained facilities.

For your information and record.


ARLENE V. FRANCISCO

National Road, Brgy. Sto. Niño, Sablayan, Occidental Mindoro
E-mail: cenrosablayan@denr.gov.ph



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE



Photos of monitoring station located at Sitio Hinugasan, Brgy. Harrison,
Paluan, Occidental Mindoro

W



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE



Photos of monitoring station located at Sitio Calangigan, Brgy. Harrison,
Paluan, Occidental Mindoro

W



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE



Photos of monitoring station located at Sitio Pinagbayanan, Brgy. Harrison,
Paluan, Occidental Mindoro

N



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE



Photos of MCWS Ranger Station located at Sitio Ulasan, Brgy. Harrison
Paluan, Occidental Mindoro

W