

Republic of the Philippines

Department of Environment and Natural Resources

Provincial Environment and Natural Resources Office MIMAROPA Region

1 0 OCT 2022

Bgy. Sta. Monica, Puerto Princesa City, Palawan

E-mail: penropalawan@denr.gov.ph Telfax No. (048) 433-5638 / (048) 433-5638

I INCOMING

OUTGOING

DATS NO.

October 04, 2022

MEMORANDUM

FOR

The Regional Executive Director

DENR MIMAROPA

1515 L&S Bldg., Roxas Blvd.

Ermita, Manila

THRU

The OIC, ARD for Technical Services

FROM

The Provincial Environment and

Natural Resources Officer

SUBJECT

REPORT ON MAINTENANCE OF FACILITIES (BIRDWATCH

TOWER AND PAMO BUILDING) IN RASA ISLAND WILDLIFE

SANCTUARY

Forwarded is the memorandum dated September 23, 2022 of CENRO Quezon along with the report on maintenance of facilities (bird watch tower and PAMO building) in Rasa Island Wildlife Sanctuary that serves as **Means of Verification (MOV)** to the target activity under 001 Protected Area Management and Development – Ecotourism Program – Maintenance of facility in RIWS.

Report revealed that the maintenance of Bird-Watch Tower in RIWS started on August 15, 2022 and finished on August 26, 2022. Moreover, the repainting of the roof and installation of two (2) window grills was already completed. However, the repainting of PAMO Building is still on-going.

For information and record.



FELIZARDO B. CAYATOC

DENR-PALAWAN
PENRO-RECORDS

RELEASED

By Phea
Date: 05 OCT 2022 2024 2666



Republic of the Philippines Department of Environment and Natural Resources MIMAROPA Region

COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE

National Highway, Bgy. Alfonso XIII, Quezon, Palawan Email: cenroquezon@denr.gov.ph

September 23, 2022

MEMORANDUM

FOR

The Provincial Environment and

Natural Resources Officer

Sta. Monica, Puerto Princesa City, Palawan

FROM

The Community Environment and

Natural Resources Officer

SUBJECT

REPORT ON MAINTENANCE OF FACILITIES (BIRD-

WATCH TOWER AND PAMO BUILDING) IN RASA ISLAND


WILDLIFE SANCTUARY

Respectfully forwarded is the Memorandum dated September 20, 2022 of Assistant Protected Area Superintendent of Rasa Island Wildlife Sanctuary regarding the above mentioned subject with attachment.

Please be informed that the maintenance for the Bird-Watch Tower in RIWS started on August 15, 2022 and finished on August 2, 2022. Further, repainting of the roofing, installation of two(2) window grills was already finished but the repainting inside the PAMO Building is still on-going.

For your information and record.

LEONARD T. CALUYA



COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE PROTECTED AREA MANAGEMENT OFFICE – RASA ISLAND WILDLIFE SANCTUARY

National Highway, Antipuluan, Narra, Palawan Contact No.: 0917-160-4920

Email: rasaislandwildlifesanctuary@gmail.com

September 20, 2022

ISLAND

MEMORANDUM

FOR

: The Community Environment and

Natural Resources Officer

Quezon, Palawan

FROM

: The Rasa Island Wildlife Sanctuary

Protected Area Superintendent

SUBJECT

: REPORT ON MAINTENANCE OF PA FACILITIES (BIRD-WATCH


TOWER AND PAMO BUILDING) IN RASA

WILDLIFE SANCTUARY

Respectfully forwarded is the report of PAMO staff re: Maintenance of PA Facilities (Bird-watch Tower and PAMO Building) in Rasa Island Wildlife Sanctuary.

For your information, reference, and further instruction.

MA. TERESA V. AYSON PASu, RWS



COMMUNIT PROTECTED AREA I

Republic of the Philippines Department of Environment and Natural Resources MIMAROPA Region

COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE PROTECTED AREA MANAGEMENT OFFICE – RASA ISLAND WILDLIFE SANCTUARY

National Highway, Antipuluan, Narra, Palawan Contact No.: 0917-160-4920

Email: rasaislandwildlifesanctuary@gmail.com

September 19, 2022

MEMORANDUM

FOR

The Protected Area Superintendent

Rasa Island Wildlife Sanctuary

FROM

The Protected Area Management Office -

Rasa Island Wildlife Sanctuary Personnel

SUBJECT

REPORT ON MAINTENANCE OF PA FACILITIES (BIRD-WATCH

TOWER AND PAMOBUILDING) IN RASA

ISLAND

WILDLIFE SANCTUARY

In reference to the Maintenance of Facilities activity under the Ecotourism Program of the approved FY 2022 Physical and Financial Plan for proclaimed and legislated Protected Areas, please be informed that the maintenance of Bird-watch tower in Rasa Island Wildlife Sanctuary started on August 15, 2022 and was finished on August 26, 2022.

On August 27, 2022, the maintenance activity in PAMO Building already started. Repainting of roofing was already finished, two (2) window grills was installed, and painting inside the building is currently on-going.

Relevant photos are attached.

For information and record.

Prepared by:

NIÑA LIZA B. NAVANES Coastal Extension Officer JERRY P. BAUTISTA FR/APASU, RIWS

Republic of the Philippines Department of Environment and Natural Resources MIMAROPA Region COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE

PROTECTED AREA MANAGEMENT OFFICE - RASA ISLAND WILDLIFE SANCTUARY

National Highway, Antipuluan, Narra, Palawan Contact No.: 0917-160-4920

Email: rasaislandwildlifesanctuary@gmail.com

September 19, 2022

DENR, FAO-RIWS

MEMORANDUM

FOR

The Protected Area Superintendent

Rasa Island Wildlife Sanctuary

FROM

The Protected Area Management Office

Rasa Island Wildlife Sanctuary Personnel

SUBJECT

:

REPORT ON MAINTENANCE OF PA FACILITIES (BIRD-WATCH

TOWER AND PAMOBUILDING) IN RASA

WILDLIFE SANCTUARY

In reference to the Maintenance of Facilities activity under the Ecotourism Program of the approved FY 2022 Physical and Financial Plan for proclaimed and legislated Protected Areas, please be informed that the maintenance of Bird-watch tower in Rasa Island Wildlife Sanctuary started on August 15, 2022 and was finished on August 26, 2022.

On August 27, 2022, the maintenance activity in PAMO Building already started. Repainting of roofing was already finished, two (2) window grills was installed, and painting inside the building is currently on-going.

Relevant photos are attached.

For information and record.

Prepared by:

NA LIZA B. NAVANES Coastal Extension Officer

Annex A. Photo documentation of Bird-watch Tower in Rasa Island Wildlife Sanctuary taken before the repair and maintenance activity



Annex B. Photo documentation of Bird-watch Tower in Rasa Island Wildlife Sanctuary taken after the repair and maintenance activity



Annex C. Photo documentation of Rasa Island Wildlife Sanctuary – Protected Area Management Office (PAMO Building) taken before the repair and maintenance activity



Annex D. Photo documentation of Rasa Island Wildlife Sanctuary – Protected Area Management Office (PAMO Building) taken during the repair and maintenance activity

