



Republic of the Philippines
Department of Environment and Natural Resources
Provincial Environment and Natural Resources Office
MIMAROPA Region

Bgy. Sta. Monica, Puerto Princesa City, Palawan

E-mail: penropalawan@denr.gov.ph

Telfax No. (048) 433-5638 / (048) 433-5638

October 10, 2022

MEMORANDUM

FOR : The Regional Executive Director
DENR MIMAROPA
1515 L&S Bldg., Roxas Blvd.
Ermita, Manila

THRU : The Assistant Regional Director for
Technical Services

FROM : The Provincial Environment and
Natural Resources Officer

SUBJECT : **REPORT ON THE DEMOLITION OF STRUCTURES OF MR.
RODOLFO BERNARDO AT SNAKE ISLAND, BRGY.
MANALO, PUERTO PRINCESA CITY**




Respectfully submitted the Memorandum dated October 10, 2022 from Forester Arnel C. Gamutia, OIC-Chief, Monitoring and Enforcement Section and Data Manager Julius F. Landrito regarding the above-mentioned subject.

As per report, a team comprised of personnel from PENRO-Palawan, Snake Island Management Office, CENRO-Puerto Princesa, represented by Forest Rangers Neil James Verzosa and Jeffrey Modesto, and Kgw. Bernardo Magbanua of Brgy. Manalo traveled on October 5, 2022 to Snake Island in the area where the structures of Mr. Bernardo were built to witness the demolition of the existing post that is still standing in the area. Based on visual inspection, four (4) posts have already been demolished, and one (1) post remains standing, which the SIMO has asked to serve as support for the signage that will be installed in the area. After the demolition, the SIMO personnel installed the signage in the vicinity of Mr. Bernardo's demolished premises on October 7, 2022. This signage will inform everyone that the area is part of Snake Island, which is managed by this office.

Attached herewith are the report and photo documentation that will be used as proof that the demolition of Mr. Bernardo's existing structure at Snake Island was witnessed and inspected by this office.

For your information and further instructions.



FELIZARDO B. CAYATOC

2022-01306



Republic of the Philippines
Department of Environment and Natural Resources
Provincial Environment and Natural Resources Office
MIMAROPA Region
Bgy. Sta. Monica, Puerto Princesa City, Palawan
E-mail: penropalawan@denr.gov.ph
Telfax No. (048) 433-5638 / (048) 433-5638

October 10, 2022

MEMORANDUM

FOR : The Provincial Environment and
Natural Resources Officer

THRU : The Chief,
Conservation and Development Section/ SIMO

FROM : Arnel C. Gamutia
OIC-Chief, Monitoring and Enforcement Section

Julius F. Landrito
Data Manager, Snake Island NCMCR

SUBJECT : **REPORT ON THE DEMOLITION OF STRUCTURES OF MR.
RODOLFO BERNARDO AT SNAKE ISLAND, BRGY.
MANALO, PUERTO PRINCESA CITY**

Respectfully submitted is the report regarding the above-mentioned subject.

A team comprised of personnel from PENRO-Palawan, Snake Island Management Office, CENRO-Puerto Princesa, represented by Forest Rangers Neil James Verzosa and Jeffrey Modesto, and Kgwd. Bernardo Magbanua of Brgy. Manalo traveled on October 5, 2022 to Snake Island in the area where the structures of Mr. Bernardo were built to witness the demolition of the existing post that is still standing in the area. Because the intended demolition happened at low tide, the speedboat sailed further to avoid passing by the coral reefs. The team arrived at around 2:50 p.m., but the demolition had already been completed. However, Mr. Bernardo's laborers, Mr. Elizer Diocson and Mr. Edwin Diocson, both residents of Brgy. Sta. Lourdes is still in the area, waiting for the team to inspect the work they have completed. Based on a visual inspection, four (4) posts have already been demolished, and one (1) post remains standing, which the SIMO has requested to serve as the support for the signage that will be placed in the area. According to Mr. Edwin Diocson, they demolished the structures the other day, therefore they finished the demolition earlier than expected. After inspecting the area, the team returned to Snake Island Station and then to Honda Bay Wharf.

The SIMO personnel installed the signage in the vicinity of Mr. Bernardo's demolished premises on October 7, 2022. This signage will inform everyone that the area is part of Snake Island, which is managed by this office.

This report will be used as proof that the demolition of Mr. Bernardo's existing structure at Snake Island was witnessed and inspected by this office. Attached herewith are the photo documentations.



Republic of the Philippines
Department of Environment and Natural Resources
Provincial Environment and Natural Resources Office
MIMAROPA Region


Bgy. Sta. Monica, Puerto Princesa City, Palawan

E-mail: penropalawan@denr.gov.ph

Telfax No. (048) 433-5638 / (048) 433-5638

For record, information, and further instructions.

Prepared by:



ARNEL C. GAMUTIA

Forester II


OIC-Chief, Monitoring and Enforcement Section



JULIUS F. LANDRITO

Data Manager, SI NCMCR

Noted by:



RHODORA B. UBANI
Chief, CDS/SIMO



PHOTO DOCUMENTATION



Photo of the team inspecting the demolition of the structures of Mr. Rodolfo Bernardo



Photo of For. Arnel C. Gamutia, inspecting the demolished posts (left); Kgwd. Magbanua and Forest Ranger Jeffrey Modesto inspecting also the demolished posts (right)




Photo of the speedboat carrying the signage (left); Photo of the signage that was already installed in the demolished structure of Mr. Bernardo (right)