



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
PROVINCIAL ENVIRONMENT AND NATURAL RESOURCES OFFICE
Bgy. Sta. Monica, Puerto Princesa City, Palawan
Telfax No. (048) 434 - 8791
Email Add: penropalawan@denr.gov.ph

RECEIVED
10 SEP 2022

TO: INCOMING	BY:	1. OUTGOING
TO:	TIME:	DATE NO.

RECEIVED
September 12, 2022

MEMORANDUM

FOR : The Regional Executive Director
DENR MIMAROPA Region
1515 L&S Bldg., Roxas Blvd.
Ermita, Manila

THRU : The OIC, ARD for Technical Services


FROM : Provincial Environment and
Natural Resources Officer

SUBJECT : **REPORT ON THE CONDUCTED WEEKLY MONITORING
AND PATROLLING IN THE RECLAMATION AREA (BRGYs.
2, 3 AND 5) CORON, PALAWAN**

Forwarded is the Memorandum dated 1 August 2022 of CENRO Coron transmitting the appended monitoring report dated 29 July 2022 submitted by the personnel of that office in compliance to the Special Order No. 019, Series of 2022 issued by the same regarding the above subject.

It is informed that there is no activity observed in the area. However, it was monitored that waste materials are dumped and scattered in some areas of Barangay 3. This concern will be brought out to the aforesaid Barangay.

For information and record.


FELIZARDO B. CAYATOC

Copy Furnish
EMU/RGT Doc. No. 2022-7785

DENR-PALAWAN
PENRO-RECORDS
RELEASED
By Rheo
Date 13 SEP 2022 CN. 2022-2354



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA IV – B
COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE
Brgy. 5, Calamianes Island, Coron, Palawan
Telephone No. +63 917 504 2633
E-mail: cenrocoron@denr.gov.ph Website: www.denr.gov

August 1, 2022

MEMORANDUM

FOR : The Regional Executive Director
1515 L & S Bdg., Roxas Blvd.
Ermita, Manila

THRU : The Provincial Environment &
Natural resources Officer
Sta. Monica, Puerto Princesa City
Palawan

FROM : The OIC-Community Environment &
Natural Resources Officer

SUBJECT : **REPORT ON THE CONDUCTED WEEKLY
MONITORING AND PATROLLING IN THE
RECLAMATION AREA (BRGYS. 2,3 AND 5) CORON,
PALAWAN**

**DENR PENRO
PALAWAN RECORDS
RECEIVED**


BY: *[Signature]*
DATE: *08/30/2022* 22-7785

Respectfully forwarded is the attached monitoring report dated July 29, 2022 submitted by the team in compliance to CENRO Special Order No. 019, Series of 2022.

Report revealed that dumping and other reclamation activities were stopped but flooding was observed in the area due to heavy rain and inflow of sea water during high tide.

Likewise, this office also called the attention of Barangay Officials and the Local Government Unit to intensify their programs on solid waste management since improper waste disposal were observed during the monitoring.

For information and record.



[Signature]
RODNEY G. VERIAN



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA IV – B
COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE
Brgy. 5, Calamianes Island, Coron, Palawan
Telephone No. +63 917 504 2633
E-mail: cenrocoron@denr.gov.ph Website: www.denr.gov


July 29, 2022

MEMORANDUM

FOR : The OIC-Community Environment and Natural Resources Officer

FROM : The Undersigned

SUBJECT : **REPORT ON THE CONDUCTED MONITORING AND PATROLLING IN THE RECLAMATION AREA (BARANGAYS 2, 3 AND 5), CORON, PALAWAN**



This pertains to the monitoring and patrolling conducted today (July 29, 2022) at the reclamation area in Brgys. 2, 3 and 5, Coron, Palawan.

Please be informed that there is no man-made activity/s observed in the area during the monitoring, however flooding was observed due to the constant heavy rain. In addition, during high tide, the water level overflow because of the absence of seawall.




It was also observed during the monitoring and patrolling that there are waste materials that are dumped and some are scattered in Barangay 3. The undersigned advised the Environment Monitoring Officer (EnMO) to inform the concerned barangay officials regarding the matter.

Attached are the geo-tagged photos taken during the conduct of monitoring and patrolling.



For information and record.


EMMA C. FRANCISCO
Forester II


RHOLDAN D. ABAYAN
Forest Protection Officer



Geo-tagged photos taken during the monitoring and patrolling in the reclamation area of Barangays 2, 3 and 5,



Geo-tagged photos taken during the monitoring and patrolling in the reclamation area of Barangays 2, 3 and 5,