




Republic of the Philippines  
Department of Environment and Natural Resources  
MIMAROPA Region  
Provincial Environment and Natural Resources Office



September 23, 2022

**MEMORANDUM**

**FOR** : The Regional Executive Director  
MIMAROPA Region

**THRU** : The Assistant Regional Director for Technical Services

**FROM** : The In-Charge, Office of the PENRO  
Oriental Mindoro


**SUBJECT** : **SUBMISSION OF REPORT OF CENRO SOCORRO ON THE  
MONITORING OF ECOTOURISM FACILITIES WITHIN  
NAUJAN LAKE NATIONAL PARK (NLNP) FOR THIRD  
QUARTER CY 2022**

Submitted is the report of CENRO Socorro on the monitoring of ecotourism facilities within NLNP. The regular monitoring was conducted this Third Quarter CY 2022.

A total of nine (9) NLNP facilities were regularly monitored by Protected Area Management Office personnel. The maintenance of the facilities involved clearing of the surroundings, installation and repainting of PAMO enclosures and signages.

For information and record.

  
ALMA E. GIBE



DENRPENR02209000045

Tdn 2209000583  
TSD-CDS/cm

# DOCUMENT TRACKING SLIP

DENR-Oriental Mindoro

2209000581

Description: SUBMISSION OF 3rd QUARTERLY REPORT ON THE MONITORING OF ECOTOURISM FACILITIES WITHIN NAUJAN LAKE NATIONAL PARK (NLNP)

Date Created: 09-20-2022:08:22

Originating Office: CENRO-Socorro

Date Received:	Date Released:	Action Taken:
<p><i>spa</i> NOEME P. ALCANCIA In-Charge, Records Unit SEP 22 2022 Office of the PENRO Date: 9-22-22/ly TSD - 9/22/22 - W 9/22/22 1:15 PM 9:05 AM</p>		<p><i>Forwarded to office of the PENRO</i> <i>forwarded to the discharge, OTMM</i> <i>Copy CDS,</i> <i>please advise to R.O.</i> <i>please provide copy to Planning</i> <i>for MOV's</i> <i>Therly</i> <i>09/22/2022</i> <i>26</i></p>

Print



September 19, 2022

**MEMORANDUM**

**FOR** : The Regional Executive Director  
**THRU** : The PENR Officer  
**FROM** : The CENR Officer  
**SUBJECT** : **SUBMISSION OF 3<sup>rd</sup> QUARTERLY REPORT ON THE MONITORING OF ECOTOURISM FACILITIES WITHIN NAUJAN LAKE NATIONAL PARK (NLNP)**

DENR-MIMAROPA REGION	
PROVINCIAL ENVIRONMENT AND NATURAL RESOURCES OFFICE	
ORIENTAL MINDORO	
PENR TRACKING NO.	
RECEIVED BY:	<i>[Signature]</i>
DATE:	SEP 22 2022
TIME:	

Respectfully forwarding the 3<sup>rd</sup> quarterly report on the monitoring of ecotourism facilities within NLNP.

The ecotourism facilities monitored and maintained by the NLNP-Protected Area Management Office (PAMO) personnel are the following:

- 2 cottages and comfort rooms near Pungao Hot spring, Barangay Montelago, Naujan;
- 2 cottages and comfort rooms near Tagbakin Falls, Barangay Tagbakin, Pola;
- 2 cottages and comfort rooms in Minglet Forest, Barangay Mabuhay II, Socorro;
- Malabo View Deck in Barangay Malabo, Victoria;
- Protected Area Management Office, Pasi II, Socorro; and
- Bangklase in Bayani, Naujan.

The activities involved in the maintenance of PA facilities are clearing of surroundings, installation and repainting of PAMO enclosure and signages.

Attached are photos as part of the usual documentation.

For information and record.

*[Signature]*  
**RODEL M. BOYLES**



September 19, 2022

**MEMORANDUM**

**FOR :** The CENR Officer

**FROM :** Senior ECOMS / PASu, NLNP

**SUBJECT :** **SUBMISSION OF 3<sup>rd</sup> QUARTERLY REPORT ON THE MONITORING OF ECOTOURISM FACILITIES WITHIN NAUJAN LAKE NATIONAL PARK (NLNP)**

Respectfully submitting the 3<sup>rd</sup> quarterly report on the conducted monitoring of ecotourism facilities in NLNP.

Please be informed that NLNP-Protected Area Management Office (PAMO) personnel conducted regular monitoring of ecotourism facilities during the 3<sup>rd</sup> quarter of which monitoring activities and dates were listed below:

<b>Date of monitoring</b>	<b>Ecotourism facilities monitored / Location</b>
July 15, 2022	2 cottages & comfort rooms in Pungao Hotspring, Montelago, Naujan 2 cottages & comfort rooms in Minglet Forest, Mabuhay II, Socorro
July 21, 2022	Protected Area Management Office, Pasi II, Socorro
July 25, 2022	Protected Area Management Office, Pasi II, Socorro
July 26, 2022	Protected Area Management Office, Pasi II, Socorro
July 30, 2022	Signage near Protected Area Management Office, Pasi II, Socorro
August 2-3, 2022	Protected Area Management Office, Pasi II, Socorro
August 8, 2022	2 cottages & comfort rooms in Pungao Hotspring, Montelago, Naujan
August 16, 2022	2 cottages & comfort rooms in Minglet Forest, Mabuhay II, Socorro 2 cottages & comfort rooms in Pungao Hotspring, Montelago, Naujan
August 24, 2022	-2 cottages & comfort rooms in Pungao Hotspring, Montelago, Naujan
August 26, 2022	Malabo View Deck, Malabo, Victoria
August 27, 2022	Malabo View Deck, Malabo, Victoria
September 1, 2022	Bangklase, Bayani, Naujan 2 cottages & comfort rooms in Tagbakin Falls, Tagbakin, Pola



September 6, 2022

2 cottages & comfort rooms in Pungao Hotspring, Montelago, Naujan

On August 27, 2022, PAMO personnel conducted monitoring of Malabo View Deck and documented the cleared surroundings of said PA facility where a Bangkal tree plantation of the Philippine Eagles (PE) organization exists. The clearing was also initiated by the said organization. On the other hand, the PAMO personnel conducted clearing of the surroundings of Tagbakin Falls cottages and comfort rooms on September 1, 2022. The activity is done to improve and clean the vicinities for possible foreign and local visitors.

Also, during this quarter, the installation of enclosure of PAMO 2<sup>nd</sup> floor and signages were contracted by Karangyan Builders and Traders, Masipit, Calapan City.

Moreover, the Bangklase is not available for operation since the last contract for its roofing repair is still not settled.

Attached are photos during the monitoring activities.

**RICARDO R. NATIVIDAD**



Photos during monitoring of PA facilities in Montelago, Naujan on July 15, 2022



Photos during monitoring of PA facilities in Mabuhay II, Socorro on July 15, 2022






Photos during monitoring of the installation of enclosure of PAMO on July 21, 2022




Photos during monitoring of the installation of enclosure of PAMO on July 25, 2022





Photos during monitoring of the installation of enclosure on July 26, 2022



Photos during monitoring of installation of signage near PAMO on July 30, 2022






Photos during monitoring of installation of enclosure of PAMO on August 2-3, 2022



Photos during monitoring of PA facilities in Mabuhay II, Socorro on August 16, 2022






Photos during monitoring of PA facilities in Montelago, Naujan on August 16, 2022



Photos during monitoring of installed air conditioner in PAMO on August 19, 2022





Photos during monitoring of PA facilities in Montelago, Naujan on August 24, 2022



Photos during monitoring of PA facility in Malabo, Victoria on August 26, 2022



Photos during monitoring of PA facility in Malabo, Victoria on August 27, 2022





Photos during monitoring of PA facility in Bayani, Naujan on September 1, 2022



Photos during monitoring of PA facilities in Tagbakin, Pola on September 1, 2022





Photos during monitoring of PA facility in Montelago, Naujan on September 6, 2022

