




Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
PROVINCIAL ENVIRONMENT AND NATURAL RESOURCES OFFICE



AUG 25 2022

MEMORANDUM

FOR : The Regional Executive Director
DENR MIMAROPA Region
1515 L&S Bldg. Roxas Blvd . Ermita, Manila

THRU : The ARD for Technical Services

FROM : The OIC, PENR Officer

SUBJECT : REPORT ON MONITORING OF FACILITIES WITHIN
MT. CALAVITE WILDLIFE SANCTUARY FOR THIRD
QUARTER CY 2022

Respectfully forwarded herewith is the memorandum dated August 19, 2022 of PASu of Mount Calavite Wildlife Sanctuary-Protected Area Management Office (MCWS-PAMO) regarding monitoring of facilities maintained for the 3rd Quarter CY 2022.

Attached with the report are the photos of facilities maintained such as Ranger Station and three (3) monitoring stations located in Barangay Harrison, Paluan, Occidental Mindoro.

For information and record.


ERNESTO L. TAÑADA

TSD-CDS8/24/2022

Copy furnished:

1. Planning Section
2. File

So. Pag-asa, Brgy. Payompon, Mamburao, Occidental Mindoro
Email: penroccemin@denr.gov.ph



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE

August 22, 2022

MEMORANDUM

FOR : The Regional Executive Director
DENR MIMAROPA Region
1515 L&S Bldg. Roxas Boulevard
Ermita, Manila

THRU : The OIC, PENR Officer

FROM : The CENR Officer


SUBJECT : REPORT ON MONITORING OF FACILITIES WITHIN MT.
CALAVITE WILDLIFE SANCTUARY (MCWS) FOR THIRD
QUARTER CY 2022

Respectfully submitted herewith is the report of Mt. Calavite Wildlife Sanctuary Protected Area Management Office on the monitoring of facilities within MCWS.

Attached are the photos of the monitored and maintained facilities.

For your information and record.

FOR. ANASTACIO A. SANTOS, MPA





Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE

August 19, 2022

MEMORANDUM

FOR : The CENR Officer

FROM : The Protected Area Superintendent
Mt. Calavite Wildlife Sanctuary

SUBJECT : REPORT ON MONITORING OF FACILITIES WITHIN MT.
CALAVITE WILDLIFE SANCTUARY FOR THIRD QUARTER
CY 2022

Please be informed that the Mt. Calavite Wildlife Sanctuary-Protected Area Management Office conducted monitoring of facilities within MCWS for the 3rd quarter of CY 2022. The following facilities are as follows:

FACILITIES	REMARKS
1. Ranger Station (1)	Aside from its function as Ranger Station, the facility is being used as temporary office of MCWS-PAMO Staff, venue during the conduct of meetings and other activities.
2. Monitoring Stations (3)	Monitoring stations located at Sitios Kalangigan, Pinagbayanan and Hinugasan, all located in Brgy. Harrison, Paluan, Occidental Mindoro are well maintained and can be used by the PA Rangers as their temporary shelter during patrol works.

Attached are the photos of the monitored and maintained facilities.

For your information and record.


ARLENE V. FRANCISCO



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE

Figure 1. Photos of Ranger Station and three (3) monitoring stations

