



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
PROVINCIAL ENVIRONMENT AND NATURAL RESOURCES OFFICE
Bgy. Sta. Monica, Puerto Princesa City, Palawan
Telfax No. (048) 434 - 8791
Email Add: penropalawan@denr.gov.ph

DENR-MIMAROPA RECORDS SECTION
RECEIVED
05 SEP 2022
INCOMING ☐ OUTGOING ☐
SY: _____ DATE NO. _____

August 22, 2022

MEMORANDUM

FOR : The Regional Executive Director
DENR-MIMAROPA Region
1515 L and S Bldg., Roxas Boulevard
Ermita, Manila

FROM : The Provincial Environment and Natural Resources Officer

SUBJECT : UTILIZATION OF LUMBER WITH ISSUED CONFISCATION ORDER WITHIN THE AOJ OF CENRO BROOKE'S POINT

Respectfully forwarded is the memorandum from CENRO Brooke's Point dated August 09, 2022 relative the above subject.

Per memorandum, CENRO Brooke's Point had requested the twenty-eight (28) pieces of confiscated poles for the repair/renovation of Material Recovery Facility (MRF) of Patrol Base Monitoring Station in Barangay Rio Tuba, Bataraza, Palawan and the same was already repair/renovated.

Below is the list of the required supporting documents, hereto attached:

1. Justification for the repair of the MRF;
2. Sketch Plan of the MRF;
3. Bill of materials of poles for the renovation/repair of MRF;
4. Certification of CENRO that said volume of forest products is available for disposition.

For information and further instruction.


FELIZARDO B. CAYATOC

Copy Furnished
CENRO Brooke's Point, Palawan
File/2022-012ACG MES Doc. Ref. Nos. 2022-7508

DENR-PALAWAN
PENRO-RECORDS
RELEASED
By Phen
Date 23 AUG 2022 CN 2022-2142



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE
Brooke's Point, Palawan

August 9, 2022

MEMORANDUM


FOR : The Regional Executive Director
DENR MIMAROPA Region
Roxas Blvd., Ermita, Manila

THRU : The Provincial Environment and
Natural Resources Officer
Puerto Princesa City

FROM : The Community Environment and
Natural Resources Officer

SUBJECT : UTILIZATION OF LUMBER WITH ISSUED
CONFISCATION ORDER WITHIN THE AOJ OF CENRO
BROOKE'S POINT

DENR PENRO
PALAWAN RECORDS
RECEIVED

BY: 
DATE: 08-11-2022 22-7508

This is in connection with the Memorandum dated May 31, 2022 of the Provincial Environment and Natural Resources Officer in line with the Memorandum dated May 17, 2022 of Regional Executive Director which was received by this office on July 8, 2022 with instruction to submit the supporting documents under Memorandum Order No. 162 series of 1993.


Please be informed that this office had requested the twenty eight (28) pieces of confiscated poles for the repair/renovation of Material Recovery Facility (MRF) of our Patrol Base Monitoring Station located at Barangay Riotuba, Bataraza, Palawan.

Hereunder the list of the required supporting documents which is hereto attached:

1. Justification for the repair of the Material Recovery Facility
2. Sketch plan of the Material Recovery Facility
3. Bill of materials of poles for the repair/renovation of MRF
4. Certification of CENRO that said volume or amount of forest products is available for disposition

Further informed that to this date the subject MFR was already renovated/repared using the said forest products.

For his information and record.



CONRADO M. CORPUZ



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE
Brooke's Point, Palawan

July 12, 2022

JUSTIFICATION


1. The DENR-CENRO Patrol Base Monitoring Station located at Barangay Riotuba, Bataraza, Palawan had established/constructed Material Recovery Facility sometimes CY 2018 as compliance of RA 9003
2. The Material Recovery Facility had been a temporary depository of segregated recyclable waste materials that can be recycle/re-use or sold to end users.
3. The construction materials previously used were made of poles and nipa shingles which to this time had been dilapidated and required repair or renovation.
4. The repair or renovation is necessary and required to serve its purpose.

CONRADO M. CORPUZ
CENRO Officer


**BILL OF MATERIALS 1 FOR THE RENOVATION/REPAIR OF MATERIAL RECOVERY
FACILITY OF RIO TUBA MONITORING STATION**

Quantity	Description	Material	Source	Measurement	Unit Price	Total cost
2	Poles	Timber	Apprehended poles	13cmx3.04m	Php. 100.00/pc.	Php. 200.00
1	Poles	Timber	Apprehended poles	17cmx2.74m	Php. 200.00/pc.	Php. 200.00
3	Poles	Timber	Apprehended poles	13cmx3.04m	Php. 200.00/pc.	Php. 600.00
22	Poles	Timber	Apprehended poles	5cmx3.04m	Php. 15.00/pc.	Php. 330.00
28	TOTAL					Php. 1,330.00

Prepared By:


KENNIT FRANCIS V. VALDESTAMON
FTII/ TL, RT MS

Attested by:


ERWIN S. VALERIANO
FI / OLC CHIEF, EMS



Republic of the Philippines
Department of Environment and Natural Resources
MIMAROPA Region
COMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE
Brooke's Point, Palawan - 5305
Email Address: cenro_brkspt@yahoo.com

CERTIFICATION


TO WHOM IT MAY CONCERN:

THIS IS TO CERTIFY that the twenty-eight pieces of assorted species of poles with a total volume of 0.245 cubic meters presently stockpiled at Rio Tuba Monitoring Station located in Baranagy Rio Tuba, Bataraza, Palawan is available for disposition.

Further certifies that corresponding Confiscation Order of the subject forest product was already issued by then Regional Executive Director Maria Loudes G. Ferrer dated May 6, 2021.

Issued this 2nd day of July 2022 at CENRO Brooke's Point, Palawan.


CONRADO M. CORPUZ
CENRO



Sketch plan of Material Recovery Facility of Rio Tuba Monitoring Station at Brgy. Rio Tuba, Bataraza, Palawan.

Prepared By:

KENNIT FRANCIS V. VALDESTAMON

Attested by:

FRANCIS VALERIANO
FI/BUTHER, EMS