



Republic of the Philippines
Department of Environment and Natural Resources
PENRO MARINDUQUE

DENR MIMAROPA RECORDS SECTION	
RECEIVED	
BY:	<i>[Signature]</i>
DATE:	APR 24 2023
TIME:	

March 10, 2023

MEMORANDUM

**FOR : The Regional Executive Director
DENR, MIMAROPA Region**

**THRU : The Assistant Regional Director
for Technical Services**

FROM : The OIC, PENR Officer

**SUBJECT : MAINTENANCE OF DEMARCATED MONUMENTS,
SIGNAGES, INFRASTRUCTURES AND FIXTURES IN
PROTECTED AREA MANAGEMENT OFFICE (PAMO) -
MARINDUQUE WILDLIFE SANCTUARY (MWS) FOR THE
FIRST QUARTER, CY 2023.**

Respectfully forwarded is the Memorandum Report from PAMO regarding Maintenance of Demarcated Monuments, Signages, Infrastructures and Fixtures in Protected Area Management Office (PAMO)- Marinduque Wildlife Sanctuary (MWS) for the 1st Quarter, CY 2023 dated March 8, 2023 together with geotagged photos of demarcated monuments, signages, infrastructures and fixtures.

For information, record and further instruction.

[Signature]
IMELDA M. DIAZ



Republic of the Philippines
Department of Environment and Natural Resources
PENRO MARINDUQUE


MEMORANDUM

FOR : **The OIC, PENR Officer**
Boac, Marinduque

THRU : **The Protected Area Superintendent**
Marinduque Wildlife Sanctuary

FROM : **The Park Maintenance Foreman**

SUBJECT : **MAINTENANCE OF DEMARCATED MONUMENTS, SIGNAGES, INFRASTRUCTURES AND FIXTURES IN MARINDUQUE WILDLIFE SANCTUARY (MWS) AS OF 1st QUARTER, CY 2023.**



In connection to the target of Protected Area Management Office (PAMO) under Protected Areas Development and Management/ Ecotourism Development/ Maintenance of Signages/ Billboards Management, please be informed that 18 concrete signages, 408 corner/ monuments and 283 newly installed signages within MWS boundaries and strategic places have been continuously maintained and protected including existing infrastructures, furnitures and fixtures in MWS as of 1st Quarter of Calendar Year 2023.

Be informed further that the maintenance and protection of the signages and infrastructure are regularly undertaken with the assistance of 3 Park Rangers, 6 Biodiversity Protection Assistants, 4 Forest Protection Officers, 1 Tourism Aide and 1 PAM Office Caretaker/Utility. Please find attached tabulated detailed information of said activities and geotagged photos for further reference.

For information, record and further instruction.


RODERICK S. VILLANUEVA

Particulars	Location and Quantity	Qty.	Total Cost	Date of Completion	Maintenance Work Conducted	Remarks
A. Signages						
A.1 Concrete Along the National Road at Barangays	1) Daykitin Buenavista	2	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	2) Malbog, Buenavista	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	3) Malibago, Torrijos	2	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	4) Poblacion, Torrijos	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	5) Taytay, Sta. Cruz	2	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	6) Tumagabok, Boac	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	7) Sili, Buenavista	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
Along the perimeter boundary of the Marinduque Wildlife Sanctuary at Barangays	1) Bagtingon, Buenavista	2	11,000.00	2017	For repair/ Damaged by Typhoon PAENG	monitored
	2) Malbog, Buenavista	1	5,500.00	2017	For repair/ Damaged by Typhoon PAENG	monitored
	3) Tumagabok, Boac	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	4) Tambunan, Boac	1	5,500.00	2017	Repaired/ Repainted	monitored/ maintained
	5) Canat Boac	1	5,500.00	2017	For repair/ Damaged by Typhoon PAENG	monitored
	6) Malibago, Torrijos	1	5,500.00	2017	For repair/ Damaged by Typhoon PAENG	monitored
	7) Sibuyao, Torrijos	1	5,500.00	2017	For repair/ Damaged by Typhoon PAENG	monitored
A.2 Newly Installed MWS Concrete Signages	23 Barangays of MWS	283		2022	Newly installed	monitored/ maintained
A.2 Wood	1) PAMO Ecotourism Satellite Office at PENRO Compound	1	3,200.00	2017	Repaired/ Repainted	maintained
	2) PAMO Information Board 3) Ecotourism Information Center - PAMO at Tumagabok, Boac	1 1	3,200.00 3,200.00	2017	Repaired/ Repainted For repair/ Damaged by Typhoon PAENG	maintained monitored
A.3 Tarpaulin	Rate of fees and rules and regulations in ecotourism at Tumagabok, Boac.	3	2,800.00	2018		maintained
A.4 Concrete Monuments	Demarcated Boundaries of MWS (Parcel 1 and 2)	408		2020-2022	Newly installed	monitored/ maintained
B. Infrastructure/ Buildings						
B.1 Ecotourism Information Center	PAMO Tumagabok, Boac	1	1,200,000.00	2016	-Renovated/ Repainted -Corrugated Sheets to Color Roof -Wood Trusses to Steel trusses	maintained

B.2 PAMO with 2.5 KW Solar Panel Energy	PAMO Tumagabok, Boac	1	1,620,000.00	2016	For repair/ Replacement of various parts (Solar Panel)	Solar Panel has been damaged by typhoon thunder/ lightning. Affected parts were battery, inverter and controller
B.3 PAMO Ecotourism Information Satellite Office	PENRO Compound, Boac	1	350,000.00	2018	-Repaired/ Improved - Rough Cement Floor to Floor Tiles - Floor Area has been extended	monitored/ maintained
B.4 Multi Purpose Building with 530 watts Solar Panel	PAMO Tumagabok, Boac	1	800,000.00	2018	-For repair/ Replacement of various parts (Solar Panel)	Solar Panel has been damaged by typhoon, thunder/ lightning. Affected parts were battery, inverter and controller.
C. Water System	Water System for PAMO, Ecotourism Center and Multi- Purpose Hall at Tumagabok, Boac	1	75,000.00	2017	Maintenance of Cleanliness and installation of water pipe lines.	monitored/ maintained
D. View deck	1. Tumagabok, Boac	1	2016	150,000.00	- Renovated - Maintenance of cleanliness in the surroundings. -From light materials to steel concrete/materials	monitored/ maintained
E. Ranger Station	2. Mt. Natilus, Bagtingon, Buenavista	1	2016	120,000.00	-Damaged by typhoon in 2019.	For repair
	1. Balagbag Mountain Range, Malibago, Torrijos	1	2018	110,000.00	-Repaired - Maintenance of cleanliness in the surroundings. Grasscutter was used in cleaning.	monitored/ maintained
	2. Mt. Natilus, Bagtingon, Buenavista	1	2016	60,000.00	-Damaged by typhoon in 2019.	For repair
E. Registration booth	Ecotourism Tumagabok, Boac	1	2018	70,000.00	-Repainted	maintained
F. Additional Kitchen	PAMO Office Tumagabok, Boac	2	2017	150,000.00	-Repainted	maintained
G. Parking shed	PENRO Compound, Boac	1	2016	200,000.00	-Maintenance of cleanliness	maintained
H. Outdoor Comfort rooms	Ecotourism Center Tumagabok, Boac	1	2018	150,000.00	-Maintenance of cleanliness	maintained
I. Vegetation plot	PAMO Tumagabok, Boac	2 has.	2017	70,000.00	-Maintenance of cleanliness	monitored/ maintained
J. Concrete Picnic Table	PAMO Tumagabok, Boac	5 has.	2018	35,000.00	-Maintenance of cleanliness	maintained

K. Concrete Steps	PAMO Tumagabok, Boac	289 steps	2017	30,000.00	-Maintenance of cleanliness	maintained
L. Eco Trail	PAMO Tumagabok, Boac	1.5 kms.	2017	25,000.00	-Maintenance of cleanliness	maintained
M. Wooden Furnitures and Fixtures			2018			
M.1 Tables			2018			
M.1.1. Office Tables	PAMO Tumagabok, Boac PAMO Satellite Office Boac	22 6	2018 2018		Revarnished Revarnished	maintained maintained
M.1.2. Kitchen Table	PAMO Tumagabok, Boac	2	2018		Revarnished	maintained
M.1.3. TV Table	PAMO Tumagabok, Boac	2	2018		Revarnished	maintained
M.1.4. Information Table	PAMO Tumagabok, Boac	1	2018		Revarnished	maintained
M.1.5. Long Table	PAMO Satellite Office Boac	2	2018		Revarnished	maintained
M.1.6. Computer Table (for 3 PC)	PAMO Satellite Office Boac	1	2018		Revarnished	maintained
M.1.7. Benches without backrest	PAMO Tumagabok, Boac	5	2018		Revarnished	maintained
M.1.8. Benches with Backrest	Brgy. Tumagabok, Boac PAMO Satellite Office Boac	14 2	2018 2018		Revarnished Revarnished	maintained maintained
M.1.9. Suggestion Box	PAMO Tumagabok, Boac	1	2018		Revarnished	maintained
M.1.10. Butress Bench/ Chair	PAMO Tumagabok, Boac	2	2018		Revarnished	maintained
M.1.11. Rostum	PAMO Tumagabok, Boac	1	2018		Revarnished	maintained
M.1.11. Office Chairs	PAMO Tumagabok, Boac PAMO Satellite Office Boac	38 12	2018 2018		Revarnished Revarnished	maintained maintained
M.1.12. Kitchen Chairs	PAMO Tumagabok, Boac	3	2018		Revarnished	maintained
M.1.13. Bookshelf	PAMO Satellite Office Boac	1	2018		Revarnished	maintained

Prepared by:


RODERICK S. VILLANUEVA
P&K Maintenance Foreman


Checked/Verified by:


EMETERIO M. RECTO
SEMS/PASu


Noted by:


IMELDA M. DIAZ
OIC – PENR Officer

CONCRETE SIGNAGES




Brgy. Taytay, Sta. Cruz



Brgy. Daykitin, Buenavista

1



Brgy. Malbog, Buenavista



Brgy. Malibago, Torrijos



Brgy. Sihi, Buenavista



Brgy. Malibago, Torrijos



Brgy. Tumagabok, Boac



Brgy. Antipolo, Gasan



Brgy. Nangka, Torrijos



Brgy. Tambangan, Sta. Cruz



Brgy. Tambunan, Boac



Brgy. Boi, Boac



Brgy. Bayuti, Boac



Brgy. Makulapnit, Sta. Cruz

9



Brgy. Poblacion, Torrijos



Brgy. Masalukot, Sta. Cruz



Brgy. Malbog, Buenavista

WOOD SIGNAGES



accuracy: 3m



2/28/23
2:46 PM

accuracy: 2m



2/28/23
2:47 PM

Altitude
454 m

2/26/26
2:48 PM


PAMO ECOTOURISM INFORMATION CENTER



PROTECTED AREA MANAGEMENT OFFICE



SOLAR PANEL



PAMO SATELLITE OFFICE



9

Multi-Purpose Building with 530 watts Solar Panel



WATER SYSTEM



8

VIEW DECK



RANGER STATION

51 P 890781 1469828

accuracy: 2m



51 P 890789 1469820

accuracy: 2m



51 P 890779 1469820

accuracy: 2m



Brgy. Malibago, Torrijos

9

RANGER STATION



Brgy. Bagtingon, Buenavista (Mt. Natilus)

REGISTRATION BOOTH



1

ADDITIONAL KITCHEN




PARKING SHED



OUTDOOR COMFORT ROOM



VEGETATION PLOT



CONCRETE STEPS



ECO TRAIL



FURNITURE AND FIXTURE















9
















9








9





Handwritten mark.





9