

Republic of the Philippines Department of Environment and Natural Resources

Provincial Environment and Natural Resources Office MIMAROPA Region

Bgy. Sta. Monica, Puerto Princesa City, Palawan E-mail: penropalawan@denr.gov.ph
Telfax No. (048) 433-5638 / (048) 433-5638

10

MEMORANDUM

FOR

The Regional Executive Director

DENR MIMAROPA Region 1515 DENR by the Bay Building,

Roxas Boulevard, Bgy 668, Ermita, Manila

FROM

The Provincial Environment and

Natural Resources Officer

SUBJECT

.

REPORT ON THE CONDUCTED WATER QUALITY RESAMPLING AT EL NIDO SEWAGE AND SOLID WASTE TREATMENT PLANT (ENSSWTP) LOCATED AT SO. BATBAT, BARANGAY VILLA LIBERTAD,

EL NIDO, PALAWAN

DATE

June 9, 2013

Forwarded is the memorandum dated May 31, 2023 from Mariano P. Lilang, Jr, Development Management Officer IV/OIC, CENRO Taytay regarding the activity as per WFP 2023, on Water Quality Monitoring within Legislated PA.

As per report submitted by the PASu of ENTMRPA Mildred A. Suza, monitoring activity were conducted by the PAMO staff together with EMS Chief Nicaith Trisha Erile of PEMU-Palawan and representative from ENSSWTP Engr. Aerol Carandang. Resampling activity was purposely done to determine if the water discharge from their project is within the water quality guidelines. Furthermore, the activity is not included in the 48 sampling sites being regularly monitored by EMB and PAMO ENTMRPA.

For information and record.



FELIZARDO B. CAYATOC



Republic of the Philippines

Department of Environment and Natural Resources

Region IV- MIMAROPA

OMMUNITY ENVIRONMENT AND NATURAL RESOURCES OFFICE

by the National Highway, Poblacion, Taytay, Palawan 5312 Contact No.: 09265059335 (Globe) / 09121713889 (Smart)

Email address: cenrotaytay@denr.gov.ph

PALAWAY REGORDS

May 31, 2023

MEMORANDUM

34: DATE: DE DE 2022 DE 23. ST75

FOR

The Provincial Environment and Natural Resources Officer- Palawan

FROM

The Community Environment and Natural Resources Officer

SUBJECT

ACCOMPLISHMENT REPORT ON ACTIVITY PER WFP

El Nido Managed Resource Protected Area (ENMRPA)

Activity: Water Quality Monitoring within Legislated NIPAS PAs

Performance Indicator: Number of PAs monitored on water quality parameters with monthly monitoring of forty-eight (48) stations and quarterly report

Current submission:

Memo report of Protected Area Superintendent/SvEMS Mildred A. Suza dated May 18, 2023 (CN 3422 in the eDATS) submitting the Water Quality re-sampling at El Nido Sewage and Solid Waste Treatment (ENSSWTP) located at Sitio Batbat, Barangay Villa Libertad, El Nido, Palawan.

Attachment:

- 1. Memo report of Park Ranger Steven John B. Andao dated May 17, 2023. Accordingly the activity conducted is not included in the forty-eight (48) monitoring stations established by the PEMU-Palawan.
- 2. Photo documentation

3. Water Quality Monitoring field data form

Gender & Development	Male $= 2$	Female = 1	LGBTQ+=0	Prefer not to say $= 0$				
(GaD) data								
	60 and	18-59	17 and below	TOTAL				
Age Grouping	above							
	0	3	0	3				
Environmental	✓ Compliant to 5S organization techniques (SORT – keep only							
Management System	necessary items, SET IN ORDER – arrange items to promote							
(EMS Compliance	efficient workflow, SHINE – clean the work area so it is neat							
	and tidy, STANDARDIZE – set standards for a consistently							
	organized workplace and SUSTAIN - maintain and review							
	standard)						

Explanation: The Water Quality Monitoring of forty-eight (48) stations as indicated in the Work and Financial Plan CY 2023 of ENTMRPA is accordingly to be conducted and funded by the EMB. The activity made by the PAMO is outside the forty-eight (48) stations. It is also hereby informed/iterated that ENTMRPA is not yet a legislated PA.

This shall form as part of the Means of Verification (MoV) on the activity. Please confirm your receipt hereof. Thank you.

DENR CENRO
TAYTAY, PALAWAN
RELEASED
BY:
DAI: JUN 01 2023 2008

For and in the absence of the CENRO:

MARIANO P. LILANG, JR.

Development Management Officer IV
Per DAO-2022-09, page 3

Copy furnished: PAMO-ENMRPA



Republic of the Philippines Department of Environment and Natural Resources

MIMAROPA Region

Community Environment and Natural Resources Office

EL NIDO MANAGED RESOURCE PROTECTED AREA

Calle Real, Bgy. Masagana, El Nido, Palawan 5313 Landline: 048-716-0674

Email: denrpao elnidopal@yahoo.com / entmrpa@gmail.com

MEMORANDUM

FOR

The Community Environment and

Natural Resources Officer

Taytay, Palawan

FROM

The Protected Area Superintendent

El Nido Managed Resource Protected Area

SUBJECT

REPORT ON THE CONDUCTED WATER QUALITY

RESAMPLING AT EL NIDO SEWAGE AND SOLID WASTE TREATMENT PLANT (ENSSWTP) LOCATED AT SO. BATBAT, BARANGAY VILLA LIBERTAD, EL

NIDO, PALAWAN.

Respectfully forwarded is the memorandum report dated May 17, 2023 of Park Ranger, Mr. Steven John B. Andao regarding the above subject.

Please be informed the ENMRPA-PAMO staff together with EMS Chief, Taytay Ms. Nicaith Trisha Erile of PEMU-Palawan and representative from ENSSWTP Engr. Aerol Carandang conducted water quality resampling to determine if the water discharge from their project is within the water quality guidelines.

The team collected 1, 000ml of water samples and send to EMB-MIMAROPA Regional Office for Laboratory analysis. They already conducted on-site parameters test using Water Quality Multi Parameter Checker (HORIBA U50G) particularly the pH, Temperature, Dissolved Oxygen, Conductivity, Salinity, Total Dissolved Solids and Turbidity. This office requested the copy furnish of the result for record and future reference as well as the analysis of the water quality results.

This serve as additional Means of Verification (MOV) for water quality monitoring as this activity is not included in the forty-eight (48) sampling sites being monitored by EMB and PAMO-ENMRPA regularly.

For information and record.



Republic of the Philippines Department of Environment and Natural Resources MIMAROPA Region

Community Environment and Natural Resources

EL NIDO-TAYTAY MANAGED RESOURCE PROTECTED AREA

Calle Real, Barangay Masagana, El Nido, Palawan, 5313 Contact No. LANDLINE (0487160674)

Email: denrpao elnidopal@yahoo.com / entmrpa@gmail.com

May 17, 2023

MEMORANDUM

FOR :

.

The Protected Area Superintendent

El Nido Managed Resource Protected Area

FROM

Park Ranger

El Nido Managed Resource Protected Area

SUBJECT: REPORT ON THE CONDUCTED WATER QUALITY

RESAMPLING AT EL NIDO SEWAGE AND SOLID WASTE TREATMENT PLANT (ENSSWTP) LOCATED AT SO. BATBAT,

BRGY. VILLA LIBERTAD, EL NIDO, PALAWAN

Please be informed that on May 16, 2023 the undersigned together with the EMS Chief, Taytay Ms. Nicaith Trisha Erile of PEMU-Palawan together with the representative from ENSSWTP Engr. Aerol Carandang conducted water quality resampling to determine if the water discharge from their project is within the water quality guidelines pursuant to DENR Administrative Order (DAO) 2016-08 for Water Quality Guidelines and General Effluent Standards of 2016.

Grabbing of collected 1,000 ml of water sample was conducted by Ms. Enrile and proper preservation of sample was also administered such as pouring of acid in the specimen and secured it in iced container. On-site parameters test was conducted by the undersigned using Water Quality Multi Parameter Checker (HORIBA U50G) particularly the pH, Temperature, Dissolved Oxygen, Conductivity, Salinity, Total Dissolved Solids and Turbidity.

The sample was sent to EMB-MIMAROPA Regional office for laboratory analysis. Ms. Enrile was advised that the result of the laboratory analysis be furnish to this office for record and future reference. Attached herewith are the geotagged photos and field data for reference.

For information and record.


STEVEN JOHN R ANDAO

PHOTO DOCUMENTATION











CERTIFICATION

This is to certify that the above photos were true and correct and taken during the conducted water quality resampling in El Nido Sewage and Solid Waste Treatment Plant (ENSSWTP) on May 16, 2023 together with EMB-PEMU Palawan personnel and representative from ENSSWTP.

STEVEN JOHN B. ANDAO Park Ranger

Control No.: __

] Influent		Abstr	DATA FOR! acted Water Q Effluent		oring eacted			
Sample ID: Stablishn Type of Industry: Location: Sa . 2	Treether	Nido E/		the second of second second	Station No.: Solid K	Priste '	Touthant Plant		
Coordinates (GPS): Date of Sampling: Name of Receiving	Latitude: S//L/19 Body of Wa	ter: _	ŧ1	Lo	ngitude:	sification	: <u>SB</u>		
Weather Condition Visual Color of San Estimated Flow Rat Observation of Suri	iple:	eat 6p	erad		of Sample: _	Non	<u> </u>		
; On-Site Tests:									
Parameter	Unit	Tes	t 1	Test 2	Test 3	Averag	ge Test Method		
рН		6:	55_	6.K	6.18				
Temperature		34.	SHOULD AND THE PROPERTY AND ADDRESS.	33.73	33.88				
Dissolved Oxygen		6.8	29	6.60	6.70				
Conductivity		Contract Con		6.47	0.766				
Salinity		6. =	Registerior State Market States Annual States	6.48	0.47				
Total Dissolved Solids		0-6	53	0.624	0.618				
Turbidity		6.7	39	5./6	3.12				
Sample for Laboratory Analysis: Type of Sample: Single Sample Duplicate Split Others:									
Parameters for Analysis	Sample Vol (mL)	lume	Cor	ntainer Type	Sampling 1	Method	Preservation		
Oil orrase	+ 1,000		9/155		grab		Wed '		
Olov Je							acidified		
Sampled by: Nicarth Enrily					Signature:		20/		
Analyzed on-site by: Stra John Andro					Signature:	Q	while		
Conforme: <u>Aero Carandarg</u> Project Development Officer				Signature:		3)-			