



Republic of the Philippines
Department of Environment and Natural Resources
Region IV- MIMAROPA
Provincial Environment and Natural Resources Office

24 May 2023

MEMORANDUM

FOR : The Regional Executive Director
MIMAROPA Region

THRU : The Assistant Regional Director
Management Services

FROM : The OIC, PENRO
Calapan City

SUBJECT : SUBMISSION OF MOTOR VEHICLE INVENTORY AND
REFLEETING PLAN

DENR MIMAROPA RECORDS SECTION RECEIVED	
JUN 07 2023	
<input type="checkbox"/> INCOMING	<input type="checkbox"/> OUTGOING
BY: _____	DATE NO. _____
TIME: _____	AD

Respectfully submitting herewith the Motor Vehicle Inventory, Refleeting Plan and other documents pertaining to the aging, disposal and procurement of motor vehicle for the province of Oriental Mindoro.

E-copy of the report was also submitted to the email provided/indicated in the Memorandum dated May 12, 2023.

For reference.


ALAN VALLE



MOTORVEHICLE INVENTORY AND REFLEETING PROGRAM

DENR-PENRO ORIENTAL MINDORO

AS OF MARCH 31, 2023

NO.	PURPOSE	USE OR OFFICE DEPLOYMENT	BRAND AND MODEL, ENIGNE DISPLACEMENT AND PLATE NO.	VEHICLE CLASSIFICATION	DATE ACQUIRED	MILEAGE AND STATUS	PROPOSED ACTION	YEAR OF REPLACEMENT			
								YEAR 1 2023	YEAR 2 2024	YEAR 3 2025	YEAR 4 2026
1	For general dispatch of PENRO personnel	PENRO Property Unit	2013 MIT : STRADA GLX DSL MT ENGINE NO.: 4D56UCEE4436 PISTON DISP: 2477 CC G.V.W. 2760KGS COLOR: POLAR WHITE CONDUCTION: BV8030 CHASSIS NO MMBJNKA40DD030659 PRODUCT NO 109764 MODEL: KA4MRD Q26 PLATE NO.: SHR 849	4x 2 pick up	2013	serviceable	for repair and maintenance	1	N/A	N/A	N/A
2	For general dispatch of C-Roxas personnel	CENRO-Roxas Property Unit	TOYOTA HI-LUX, FREEDOM WHITE, MODEL 2017, CHASSIS NO. MR0CB8CD5H0402517, ENGINE NO. 2GD4306909, AOA-715	4x 2 pick up	2017	serviceable	for repair and maintenance				1
3	For general dispatch of C-Socorro personnel	CENRO-Socorro Property Unit	ISUZU, D MAX SINGLE CAB, DIESEL, PASSENGER VAN, 2014 MODEL, ENGINE NO. 4JK12X2609, CHASSIS NO. PABTFR86HE 2000169, PLATE NO. SLD 545	Multi-purpose/ passenger van	2014	serviceable	for repair and maintenance			1	
4	For general dispatch of C-Roxas personnel	CENRO-Socorro Property Unit	ISUZU D MAX SINGLE CAB, DIESEL, PASSENGER VAN, 2014 MODEL, ENGINE NO. 4JK1LX7700, CHASSIS NO. PABTFR86HE 200018, WITH PLATE NO. SLD 522	Multi-purpose/ passenger van	2014	serviceable	for repair and			1	


							maintenance				
5	For general dispatch of PENRO personnel	PENRO Property Unit	TOYOTA PICK-UP, HILUX 30, BLACK DIESEL, 2011 MODEL, ENGINE NO. 1KD5384256, CHASSIS NO. MR0F229G201627189 WITH PLATE NO. SKP 779	4x4 pick up	2011	serviceable	for repair and maintenance		1		
6	For official use of CENRO Rodel Boyles	CENRO-Socorro Property Unit Section	Mitsubishi Montero, Model 2013, Chassis no. MMBGNKH40DF005779, Engine no. 4D56UCEB7636, Color Quartz Brown Metal WITH PLATE NO. WTQ-409	SUV	07/31/2013	serviceable	for repair and maintenance				1
7	For official use of MES personnel	PENRO Property Unit	DIRT BIKE (MOTORCYCLE), ENGINE NO. KHR10E018828, CHASSIS NO: KRH10018773, YEAR MODEL: 2019, MV FILE NO. 0403-00000189820	motorcycle	10-16-2019	serviceable	for repair and maintenance				
8	For official use of MES personnel	CENRO-Socorro Property Unit	DIRT BIKE (MOTORCYCLE), ENGINE NO. KHR10E018772, CHASSIS NO: KRH10018809, YEAR MODEL: 2019, MV FILE NO. 0403-00000189821	motorcycle	10-16-2019	serviceable	for repair and maintenance				
9	For official use of MES personnel	CENRO-Socorro Property Unit	DIRT BIKE (MOTORCYCLE), ENGINE NO. KHR10E018628, CHASSIS NO: KRH10018603, YEAR MODEL: 2019, MV FILE NO. 0403-00000189824	motorcycle	10-16-2019	serviceable	for repair and maintenance				
10	For official use of MES personnel	CENRO-Roxas Property Unit	DIRT BIKE (MOTORCYCLE), ENGINE NO. KHR10E018617, CHASSIS NO: KRH10018602, YEAR MODEL: 2019, MV FILE NO. 0403-00000189818	motorcycle	10-16-2019	serviceable	for repair and maintenance				

11	For official use of MES personnel	CENRO-Roxas Property Unit	DIRT BIKE (MOTORCYCLE), ENGINE NO. KHR10E018814, CHASSIS NO: KRH10018779, YEAR MODEL: 2019, MV FILE NO. 0403-00000189823	motorcycle	10-16-2019	serviceable	for repair and maintenance				
12	For official use of Pola Watershed	CENRO-Roxas Property Unit	HONDA XR 2009 MC. RED, GAS, SK 7543 CHASSIS NO. KCN06014866 MOTOR NO. KCN06E014868	motorcycle	2013	serviceable	for repair and maintenance				
13	For official use of MES personnel	PENRO Property Unit	KAWASAKI BLACK, GAS, SK 7544 CHASSIS NO. MH41X150CC KPO8531, MOTOR NO. LX150CEP54654	motorcycle	2012	serviceable	for repair and maintenance				1
14	For official use of MES personnel	CENRO-Socorro Property Unit	HONDA TMX 1559, RED, SK 7535 CHASSIS NO. KB509345677 MOTOR NO. KB509E345678	motorcycle	2012	serviceable	for repair and maintenance				1
15	For general dispatch of C-Roxas personnel	CENRO-Roxas Property Unit	NISSAN PATHFINDER, ENGINE NO. TD2752754, CHASSIS NO. UBDM21 F70994, WITH PLATE NO. SEK 723	pick up	01-02-1998	serviceable	for repair and maintenance		1		
16	For official use of MES personnel	CENRO-Socorro Property Unit	HONDA MOTORCYCLE (BLACK) XR150L, MODEL: XR150LEKJ BK, ENGINE NO: KRH10E027844, CHASSIS NO: KRH10027891, MV FILE NO: 0403-00000265065	Motorcycle	10-07-2020	serviceable	for repair and maintenance				
17	For official use of MES	CENRO-Socorro	HONDA MOTORCYCLE (BLACK) XR150L, MODEL: XR150LEKJ BK, ENGINE NO: KRH10E027675, CHASSIS NO: KRH10027732, MV FILE NO: 0403-00000265064	Motorcycle	10-07-2020	serviceable	for				


	personnel	Property Unit	HONDA MOTORCYCLE (BLACK) XR150L, MODEL: XR150LEKJ BK, ENGINE NO: KRH10E027739, CHASSIS NO: KRH10027822, MV FILE NO: 0403- 00000265063					repair and maintenance					
18	For official use of MES personnel	CENRO-Roxas Property Unit		Motorcycle	10-07-2020	serviceable	for repair and maintenance						
19	For official use of MES personnel	CENRO-Roxas Property Unit	HONDA MOTORCYCLE (RED) XR1, MODEL: XR150LEKJ RD, ENGINE NO: KRH10E029214 CHASSIS NO: KRH10029230, MV FILE NO: 0403-00000265449	Motorcycle	10-07-2020	serviceable	for repair and maintenance						
20	For official use of MES personnel	CENRO-Socorro Property Unit	HONDA MOTORCYCLE (BLACK) XR150L, Model: XR150LEKJ BK, Engine no: KRH10E02308, Chassis no: KRH10032319, MV FILE NO: 0403-00000323517	Motorcycle	07-27-2021	serviceable	for repair and maintenance						
21	For official use of MES personnel	CENRO-Socorro Property Unit	HONDA MOTORCYCLE (RED) XR150L, Model: XR150LEKJ RD, Engine no: KRH10E033626, Chassis no: KRH10033623, MV FILE NO: 0403-00000323520	Motorcycle	07-27-2021	serviceable	for repair and maintenance						
22	For official use of MES personnel	CENRO-Roxas Property Unit	HONDA MOTORCYCLE (BLACK) XR150L, Model: XR150LEKJ BK, Engine no: KRH10E032729, Chassis no: KRH10032720, MV FILE NO: 0403-00000323519	Motorcycle	07-27-2021	serviceable	for repair and maintenance						

23	For official use of MES personnel	CENRO-Roxas Property Unit	MOTORCYCLE (RED) XR150L, Model: XR150LEKJRD, Engine no: KRH10E033574, Chassis no: KRH10033599, MV FILE NO: 0403-00000323518	Motorcycle	07-27-2021	serviceable	for repair and maintenance				
24	For official use of MES personnel	CENRO-Roxas Property Unit	KAWASAKI MOTORCYCLE (BLACK) ROOSER NS125AA, Model: RNS125-A380 BLK, Engine no: JEXWLJ32242, Chassis no: MD2B24BX0LWJ89877, MV FILE NO. 0403-00000332743	Motorcycle	07-27-2021	serviceable	for repair and maintenance				
25	For official use of MES personnel	CENRO-Roxas Property Unit	Light Cargo/ Mini Dump Truck (ISUZU), MV FILE NO. 0403-00000323701 , FUEL: DIESEL, 'YEAR MODEL: 2021, BODY TYPE: DROPSIDE, ENGINE NO. 4JJ1157U64, CHASSIS NO. PABNPR85KJM201486	Cargo Truck	09-27-2021	serviceable	for repair and maintenance				
26	For official use of PENRO Alan L. Valle	PENRO Property Unit	ISUZUD-MAX 3.0 4x4 LS E AT,DOUBLE CAB,Chassis No:MPATFS40JNT017286,Engine No. 4JJ3YR6437,CS No: D3K352 ,Color: VALENCIA ORANGE,Year Model : 2023,Fuel : Diesel	4x4 Pick up	04-04-2023	serviceable	for repair and maintenance				

Prepared by:


MYLA GEMMA P. GAMBOA
 FT II/In-Charge Property/HR

Attested by:


NESTOR N. CUASAY
 DMO IV/In-Charge, GSU

Certified Correct:


MARICEL V. SUPLEO
 Chief, Management Services Division

Region / Office: _____
(operating unit = Regional Office / PENRO / CENRO)


AGING OF MOTOR VEHICLES

As of March 31, 2023


[illegible]

more than 15 yrs old															
16 yrs. Old															
17 yrs. Old															
18 yrs. Old															
19 yrs. Old															
20 yrs. Old															
more than 20 yrs old															
21 yrs. Old															
22 yrs. Old															
23 yrs. Old															
24 yrs. Old															
25 yrs. Old															
more than 25 yrs old															
26 yrs. Old															
27 yrs. Old															
28 yrs. Old															
29 yrs. Old															
30 yrs. Old															
more than 30 yrs old															
TOTAL															


Prepared by:


MYLA GEMMA P. GAMBOA
FT II/In-Charge Property/HR

Attested by:


NESTOR N. CUASAY
DMO IV/In-Charge, GSU

Certified Correct:


MARICEL V. SUPLEO
Chief, Management Sevices Division

Annex A-2


Region / Office: _____
 (operating unit = Regional Office / PENRO / CENRO)

AGING OF MOTOR VEHICLES
 As of March 31, 2023


Type: Motorcycles/ATV and Quad bikes

4-WHEEL & ABOVE MOTOR VEHICLES	NO. OF VEHICLES (1) (1) = (2) + (3)	SERVICEABLE (2)	UNSERVICEABLE (3)	
			Repairable	For disposal
Below 5 yrs old				
1 yr. Old				
2 yrs. Old	6	6		
3 yrs. Old	4	4		
4 yrs. Old	5	5		
5 yrs. Old				
6-10 yrs old				
6 yrs. Old	1	1		
7 yrs. Old				
8 yrs. Old				
9 yrs. Old	2	2		
10 yrs. Old	3	3		
11-15 yrs old				
11 yrs. Old	4	4		
12 yrs. Old	1	1		
13 yrs. Old				
14 yrs. Old				
15 yrs. Old				
more than 15 yrs old				
16 yrs. Old				
17 yrs. Old				
18 yrs. Old				
19 yrs. Old				
20 yrs. Old				
more than 20 yrs old				
21 yrs. Old	1			1
22 yrs. Old				
23 yrs. Old				
24 yrs. Old				
25 yrs. Old	2			2
more than 25 yrs old				
26 yrs. Old				
27 yrs. Old				
28 yrs. Old				
29 yrs. Old				
30 yrs. Old				
more than 30 yrs old				
TOTAL	29			


Prepared by:


 MYLA GEMMA P. GAMBOA
 FT II/In-Charge Property/HR

Attested by:


 NESTOR N. CUASAY
 DMO IV/In-Charge, GSU

Certified Correct:



 MARICEL V. SUPLEO
 Chief, Management Services Division

Region / Office: _____
 (operating unit = Regional Office / PENRO / CENRO)


PROPOSED VEHICLE REQUIREMENT

OFFICE	OFFICIAL	STAFF	TOTAL NO. OF VEHICLE(S)	TYPE OF VEHICLE										
				Van	Pick-up	SUV	AUV	CUV	Bus/ Mini Bus	Heavy Equip- ment	MPV	Water Craft	Tri- wheeled Vehicle	Motor- cycle /ATV
PENRO														
General Services Unit		1	1			1								
Procurement														
Property														
Budget														
Planning		1	1			1								
Records														
Accounting		1	1			1								
Cashier														
Conservation Development Division		1	1		1									
Forest Production														
Coastal and Marine		1	1		1									
Protected Area Unit		1	1		1									
Enforcement Unit		1	1		1									
Total														

Prepared by:


MYLA GEMMA P. GAMBOA
 FT II/In-Charge Property/HR

Attested by:


NESTOR N. CUASAY
 DMO IV/In-Charge, GSU

Certified Correct:


MARICEL V. SUPLEO
 Chief, Management Services Division

DENR REFLEETING PROGRAM
(2022-2028)


1. DISPOSAL PLAN

TYPE OF VEHICLE	2023	2024	2025	2026	2027	2028	TOTAL
Van							
Pick-up							
SUV	1						
AUV							
CUV							
Bus/ Mini Bus							
Heavy Equipment							
MPV							
Water Craft							
Tri-wheeled Vehicle							
Motor-cycle /ATV	2						


1. PROCUREMENT PLAN

TYPE OF VEHICLE	2023	2024	2025	2026	2027	2028	TOTAL
Van							
Pick-up		1	1	1	1		
SUV		1	1	1			
AUV							
CUV							
Bus/ Heavy Equipment							
MPV							
Water							
Tri-wheeled Vehicle							
Motor-cycle							


Prepared by:


MYLA GEMMA P. GAMBOA
FT II/In-Charge Property/HR

Attested by:


NESTOR N. CUASAY
DMO IV/In-Charge, GSU

Certified Correct:


MARICEL V. SUPLEO
Chief, Management Services Division